

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1		1		1				
	Total	606	3055	2	1	2	1	2	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	8	1	8	1	8			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	8	1	8	1	8	0	0	
	Grand Total	1082	6468	3	9	3	9	3	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.12.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Suryapet	Yerkaram	33KV	Suryapet	06.10	08.25	02.15	EL	Insulator flashover	Yerkaram	-
1	RR N	132KV Medchal	33KV Aliabad	33KV	Medchal	08.41	17.30	08.49		33KV Pin Insulator failed at near by ORR, crusher(Backfeeding arranged from 33KV Aliabad Feeder from 132KV LGM Pet)	33KV Aliabad	-
1	HYD N	132KV Chilkaiguda	Patigadda	33KV	Nehru Ngr	16.23	16.33	00.10	EL,OL-Bph	No visible fault	Patigadda	Loads transferred onto 132KV Patigadda SS via 33KV Patigadda fdr

TSSPDCL - LMRC / Corporate office

Date: 02.12.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Dirsenspally	Dirsenspally	11KV	Suryapet	10.00	12.40	02.40	EL	Jumper Cut	-
2		Burugadda	Karkayalagudem	11KV	Huzurnagar	21.00	22.00	01.00	EL	Due to 11 KV Line Snapped	-
3		Mattampally	Choutupally	11KV	Huzurnagar	02.40	05.40	03.00	EL	Due to 11kv Insulator Failure.	-
4		Dondapadu	Vajinepally	11KV	Huzurnagar	10.00	12.00	02.00	EL	Due to 11kv Line Cutted	-
5		Thogarrai	GudiBanda	11KV	Huzurnagar	11.30	14.30	03.00	EL	Due to 11Kv Jumper Cuuted	-
6		Munagala	Turkagudem	11KV	Huzurnagar	07.30	10.45	03.15	EL	Due to 11Kv Jumper Cuuted	-
7		Thipparthy	Mamidala	11KV	Nalgonda	09.06	11.00	01.54	EL	11KV Jumper Cut	-
8		Singarajupally	Bramanapally	11KV	Devarakonda	00.00	08.00	08.00	EL	11KV Insulator Failed	-
1	RR E	Vasanthapuri	Sai Ram	11KV	Sainikpuri	16.47	17.54	01.07		11Kv line snapped at Janapriya Apt near Yadav Nagar (AE)	-