

Status Report on Breakdowns (Urban / Rural)**Urban**

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | 1 | | 1 | | 1 | | | | |
| 6 | RR(N) | 54 | 550 | | | | | | | | | |
| 7 | RR(E) | 168 | 403 | | 1 | | 1 | | 1 | | | |
| 8 | Hyd | 194 | 1044 | | | | | | | | | |
| | Total | 606 | 3055 | 1 | 1 | 1 | 1 | 1 | 1 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|-------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | | | | | | | | | |
| 2 | NLG | 144 | 988 | | 4 | | 4 | | 4 | | | |
| 3 | MDK | 107 | 933 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 0 | 4 | 0 | 4 | 0 | 4 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 1 | 5 | 1 | 5 | 1 | 5 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Date: 07.12.2018

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------|----------------------|------|----------------------|-------|-------|----------|------------------|--|-----------------------|---------------------------|
| 1 | RR S | MD Pally | Laxmiguda | 33KV | RJNR | 05.30 | 06.25 | 00.55 | B/D | Tree branches Fallen on 11kv line at vinayak nagar | | - |

TSSPDCL - LMRC / Corporate office

Date: 07.12.2018

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|---------------------------|
| 1 | NLG | Chandur | Angadipetea | 11KV | Nalgonda | 07.40 | 16.10 | 08.30 | EL | 11KV Line Jumper Cut | - |
| 2 | | Chandur | Kastala | 11KV | Nalgonda | 08.15 | 12.33 | 04.18 | EL | 11KV Line Jumper Cut | - |
| 3 | | Raghunadapalem | Gundlapally | 11KV | Huzurnagar | 08.00 | 10.00 | 02.00 | EL | Due to jumper cutted | - |
| 4 | | MR.Gudem | Ind | 11KV | Bhongir | 10.10 | 13.00 | 02.50 | EL | 11kv Disc Fail near Muthreddy gudem Villge | - |
| 1 | RR E | Balaji nagar | Dental collage | 11KV | Keesara | 05.35 | 06.30 | 00.55 | | Water paibe fallen on 11kv line at Vijaya nagar | - |