

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	3	0	3	0	3	0	0	
	Grand Total	1082	6468	0	7	0	7	0	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.12.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Munagala	Bharakath Gudem	11KV	Huzurnagar	11.35	12.30	00.55	EL	Due to 11Kv Line Snapped	-
2		Repala	Kalakova	11KV	Huzurnagar	15.30	17.00	01.30	EL	Due to 11Kv Jumper Cutted	-
3		Thipparthy	Mamidala	11KV	Nalgonda	09.06	11.00	01.54	EL	11KV Jumper Cut	-
1	RR S	Gandham Guda	Hydharshakote	11KV	RJNR	05.50	07.09	01.19	B/D	11KV Pole damaged at Prashanth nagar unknown vehicle dashed 11KV Jumper opened	-
1	HYD S	Vittalwadi	Y.M.C.A	11KV	II	01.45	03.05	01.20	EL,OL-R&Bph	Cable fault at Blood Bank	
2	HYD N	Bora Banda	Swaraj Nagar	11KV	IV	21.20	22.27	01.07	EL,OL	No Visible Fault	
3	HYD S	Aliabad	Shamsheergunj	11KV	III	23.10	00.15	01.05	EL	Cat fallen on Lines at Goshala	

## TSSPDCL - LMRC / Corporate office

Date: 09.12.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL					NIL		-
2	NLG				NIL					NIL		-
3	MDK				NIL					NIL		-
4	RR S				NIL					NIL		-
5	RR N				NIL					NIL		-
6	RR E				NIL					NIL		-
7	HYD				NIL					NIL		-