

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		7		7		7			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		13		13		13			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>22</b>	<b>0</b>	<b>22</b>	<b>0</b>	<b>22</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	14	45	14	45	14	45			
3	MDK	107	933		2		2		2			
4	SDPT			3	20	1	14	1	14			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>17</b>	<b>68</b>	<b>15</b>	<b>62</b>	<b>15</b>	<b>62</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>17</b>	<b>90</b>	<b>15</b>	<b>84</b>	<b>15</b>	<b>84</b>	<b>0</b>	<b>0</b>	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Nalgonda	Indoor	33KV	Nalgonda	02.40	07.25	04.45	E/L	33Kv Insulater Failed	Indoor	-
2		Kanagal	Thurkapally	33KV	Nalgonda	09.10	11.40	02.30	E/L	33Kv Jumper Cut	Thurkapally	-
3		Kanagal	Gurrampodu	33KV	Devarakonda	04.10	07.03	02.53	E/L	B/D Earth Falt	Gurrampodu	-
4		K.M.Pally	Neredugomu	33KV	Devarakonda	07.50	08.50	01.00	E/L	B/D Wind & Gale	Neredugomu	-
5		Haliya	Peddavoora	33KV	Miryalaguda	02.10	05.30	03.20	E/L	B/D Conductor Snpped Altarnet Supply 33Kv Yacharam on 05:30	Peddavoora	-
6		Suryapet	HPCL	33KV	Suryapet	07.50	08.33	00.43	E/L	Tree Fallon the line	HPCL	-
7		Suryapet	S.V.Collage	33KV	Suryapet	14.00	16.10	02.10	E/L	Tree Fallon the line	S.V.Collage	-
8		Thungathurthi	Phanigiri	33KV	Suryapet	03.25	07.30	04.05	E/L	B/D Altarnet Supply 33Kv Shaligourarm on 07:30	Phanigiri	-
9		Thungathurthi	Annaram	33KV	Suryapet	07.33	09.15	01.42	E/L	B/D Earth Falt	Annaram	-
10		Wadapally	Janphad	33KV	Huzurnagar	03.15	11.00	07.45	E/L	Tree Fallon the line	Janphad	-
11		Dirsencherla	Kethavarigudem	33KV	Huzurnagar	03.00	05.57	02.57	E/L	33Kv Insulater Failed	Kethavarigudem	-
12		Dirsencherla	Palakeedu	33KV	Huzurnagar	07.00	10.27	03.27	E/L	33Kv Insulater Failed	Palakeedu	-
13		Munagala	Nadigudam	33KV	Huzurnagar	06.15	10.00	03.45	E/L	B/D Altarnet Supply Siripuram On 23:45	Nadigudam	-
14		Kolanpaka	Alier	33KV	Bhongir	01.45	08.40	06.55	E/L	B/D Earth Falt	Alier	-
1	SDP	Siddipet	Narsapur	33KV	Siddipet	15.15	16.15	01.00		Loads transfer to peddakodur		-
2		Siddipet	Circle office	33KV	Siddipet	19.10	Still			Break Down (jumper cut)		-
3		Thunkibollaram	Sitarampally	33KV	Gajwel	20.45	Still			Break Down (tripped on EL)		-

## TSSPDCL - LMRC / Corporate office

Date: 17.12.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Ponnakal	Vemula	11KV	Jadcherla	11.25	14.30	03.05		11KV Wire cut near Vemula Village	-
1	NLG	Pamanagundla	Ismailpally	11KV	Nalgonda	22.25	08.00	09.35	EL	11 KV Insulator failed SS-20	-
2		Eduloor	Munukuntla	11KV	Nalgonda	02.45	06.30	03.45	EL	11 KV Line jumper cut nearby village	-
3		Eduloor	Eduloor	11KV	Nalgonda	08.00	11.20	03.20	EL	11 KV Insulator failed SS-36	-
4		Eduloor	G.B.Gudem	11KV	Nalgonda	06.30	14.20	07.50	EL	11KV line cut at village end	-
5		Palem	Ogodu	11KV	Nalgonda	23.05	14.00	14.55	EL	HT/LT lines melting due to heavy gale and wind and rain	-
6		Palem	Bopparam	11KV	Nalgonda	01.35	13.10	11.35	EL	HT/LT lines melting due to heavy gale and wind and rain	-
7		Rayanigudem	J.R.Gudem	11KV	Nalgonda	03.00	12.00	09.00	EL	11KV line cut at village end and 11KV Insulator failed	-
8		Koppole(K)	Bheemaram	11KV	Nalgonda	00.55	14.19	13.24	EL	11 KV Insulator failed	-
9		Ch.Annaram	G.B.Gudem	11KV	Nalgonda	04.00	16.00	12.00	EL	11 KV Insulator failed, and 11KV line cut at village	-
10		Aregudem	Chityala AGL	11KV	Nalgonda	01.30	15.00	13.30	EL	HT/LT lines melting, and 11KV line cut at village	-
11		Mushampally	Mushampally village	11KV	Nalgonda	00.00	10.00	10.00	EL	HT/LT lines melting, and 11KV line cut at village	-
12		Mushampally	Mushampally AGL	11KV	Nalgonda	00.00	09.00	09.00	EL	11 KV jumper cut	-
13		Laxmidavigudem	Ravulapenta	11KV	Miryalguda	07.00	14.00	07.00	EL	Jumper cut at Ravulapenta	-
14		Yacharam	Annaram	11KV	Miryalguda	06.00	08.10	02.10	EL	Tree Fallen in the line	-
15		Avatnhipuram	Rainipalem	11KV	Miryalguda	07.00	09.00	02.00	EL	Tree Fallen on the line	-
16		V.K.Palem	Thungapadu	11KV	Miryalguda	03.45	14.50	11.05	EL	11KV line jumper to pole	-
17		Nandipahad	Iyalapuram	11KV	Miryalguda	03.00	11.00	08.00	EL	Jumper touching to S-ph DTR pole	-
18		Damarcherla	T.v.Gudem	11KV	Miryalguda	01.00	17.10	16.10	EL	Tree branches fallen on line	-
19		A.D.Pally	Mudimanikyam	11KV	Miryalguda	07.30	15.30	08.00	EL	Jumper cut at Banjara thanda	-
20		Nidmanoor	Shakapuram	11KV	Miryalguda	07.00	11.30	04.30	EL	Tree branches fallen on line	-
21		Kothagudem	Kothagudem	11KV	Miryalguda	10.50	14.40	03.50	EL	Tree branches fallen at Maramma thanda	-
22		V.K.Palem	V K Palem	11KV	Miryalguda	17.25	18.47	01.22	EL	11KV cable fault near the Rice Mill	-
23		Matoor	Ragadapa	11KV	Miryalguda	13.30	16.50	03.20	EL	Pole leaned at Ragadapa	-
24		B Chandupatla	Thimmapuram	11KV	Suryapet	12.00	14.30	02.30	EL	Insulator flashover	-
25		Nagaram	W Kota	11KV	Suryapet	08.30	11.15	02.45	EL	Conductor Snapped	-
26		Thungathurthy	Ganugubanda	11KV	Suryapet	12.50	15.22	02.32	EL	Jumper cut	-
27		Yerkaram	Yerkaram	11KV	Suryapet	06.20	09.40	03.20	EL	Conductor Snapped	-
28		Ponugodu	Velidanda	11KV	Huzurnagar	06.00	09.30	03.30	EL	Due to 11Kv Disk failure	-
29		Huzurnagar	Y.Singaram	11KV	Huzurnagar	05.00	08.35	03.35	EL	Due to 11Kv insulator failure	-
30		Sirikonda	Sirikonda	11KV	Huzurnagar	07.00	10.45	03.45	EL	Due to Tree branch fall on 11Kv line	-
31		N.B.Gudem	N.B.Gudem	11KV	Huzurnagar	05.45	08.45	03.00	EL	Due to 11Kv insulator failure	-
32		Karivirala	Ramchandrapuram	11KV	Huzurnagar	03.45	07.00	03.15	EL	Due to Tree branch fall on 11Kv line	-
33		Ravipahad	Burkacherla	11KV	Huzurnagar	04.00	07.00	03.00	EL	Due to Tree branch fall on 11Kv line	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
34		Bollepally	Jumpally	11KV	Bhongir	04.00	09.30	04.30	EL	Due to Normal wind & Rain 11kv Insulator Fail Near Madharam Villge	-	
35		MT.pally	Mulkalapally	11KV	Bhongir	10.35	11.50	01.15	EL	11kv Insulator Fail near Milkalapally Villge	-	
36		Alair 2	Alair Agl	11KV	Bhongir	05.45	09.45	04.00	EL	11kv Discs Fail near Alair Villge	-	
37		Sharajipet	Tangtoor	11KV	Bhongir	12.25	16.00	03.35	EL	Due to Normal wind & Rain SS 7 near 11kv Disc Fail	-	
38		Pamkunta	Pamkunta	11KV	Bhongir	12.45	14.45	02.00	EL	11kv Pin Insulator Fail Pamkunta Villge	-	
39		Y.Gutta	Temple	11KV	Bhongir	04.30	08.40	04.10	EL	Due to Normal wind & Rain 11kv Disc Fail Near Telangana Hotel	-	
40		Y.Gutta	Mallapur	11KV	Bhongir	11.00	12.15	01.15	EL	Due to Normal wind & Rain 11kv Insulator Fail Near Mallapur Villge	-	
41		Azeempet	Azeempet	11KV	Bhongir	04.00	08.00	04.00	EL	Due to Normal wind & Rain 11kv Disc Fail Near Uttoor Uppalaiya well	-	
42		Azeempet	Kanchanpally	11KV	Bhongir	06.00	10.40	04.40	EL	11KV Disc Fail Near Bottu Gudem Villge	-	
43		Azeempet	Repaka	11KV	Bhongir	17.00	18.10	01.10	EL	SS-3 DTR Fail in Repaka Village	-	
44		Ishkilla	Uthatoor	11KV	Bhongir	04.30	09.30	05.00	EL	11kv Insulator Fail Near Mal bai	-	
45		Vemulakonda	Vemulakonda	11KV	Bhongir	05.10	09.00	04.50	EL	11kv Insulator Fail near Vemulakonda Wagu	-	
1		MDK	Ismailkhanpet	Industrial	11KV	Sangareddy	00.00	12.37	12.37		B/D due to 11KV 2Nos Poles Damaged at Company side	-
2			Nandigama	AV Alloys	11KV	Sangareddy	16.05	17.10	01.05		B/D due to 11KV Jumper cut at Nandigama Vg	-
1		SDP	Husnabad	Husnabad Town-1	11KV	Siddipet	10.50	10.55	00.05		BREAK DOWN	-
2	Pandilla		Pandilla Rural	11KV	Siddipet	09.15	11.00	01.45		B/D single phase ok	-	
3	Pandilla		Potlapally	11KV	Siddipet	09.15	11.53	02.38		BREAK DOWN	-	
4	Gandipally		Ramavaram Exp	11KV	Siddipet	11.40	22.40	11.00		BREAK DOWN	-	
5	Bejjanki		Kallipally	11KV	Siddipet	12.40	17.30	04.50		BREAK DOWN	-	
6	Bejjanki		Bejjanki & Rws	11KV	Siddipet	14.45	16.00	01.15		BREAK DOWN	-	
7	Bejjanki		Regulapally	11KV	Siddipet	14.40	Still			Still Now	-	
8	Ramchandrapur		Ramchandrapur Town	11KV	Siddipet	14.00	17.30	03.30		BREAK DOWN	-	
9	Ramchandrapur		Varikolu	11KV	Siddipet	18.00	Still			Single phase ok	-	
10	Koheda		Theegalakuntapally	11KV	Siddipet	09.45	13.15	03.30		BREAK DOWN	-	
11	Koheda		Sriramulapally	11KV	Siddipet	09.40	12.50	03.10		BREAK DOWN	-	
12	Shanigaram		Gundareddypally	11KV	Siddipet	10.00	Still			Single phase ok	-	
13	Baswapur		Muthannapet	11KV	Siddipet	22.45	Still			BREAK DOWN	-	
14	Cherial Town		Cherial-Town	11KV	Siddipet	03.00	04.00	01.00		BREAK DOWN	-	
15	Komuravelly		Kadavergu	11KV	Siddipet	05.40	09.45	04.05		BREAK DOWN	-	
16	Nagapuri		Pothireddypalli	11KV	Siddipet	12.00	08.00			BREAK DOWN 1ph ok	-	
17	Dhoolmitta		Arjunpatla	11KV	Siddipet	16.35	17.05	00.30		BREAK DOWN	-	
18	Gagillapur		Gagillapur Agl	11KV	Siddipet	01.00	Still			Single phase ok	-	
19	Gagillapur		Vallampatla	11KV	Siddipet	01.00	08.00	07.00		BREAK DOWN	-	
20	Marmamula		Dharmaram	11KV	Siddipet	21.00	Still			Single phase ok	-	
1		Kompally	Jaibheri	11KV	Medchal	20.39	21.50	01.11	BD	No Fault	-	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
2	RR N	Kompally	Kompally	11KV	Medchal	21.46	22.46	01.00	BD	AB Cable failed at Fish Godown, Kompally	-
3		Shameerpet	Devarayamjal	11KV	Medchal	17.22	19.30	02.08	BD	11KV Jumper cut and replaced at Outer Ring road	-
4		Gowdawelly	Gowdawelly	11KV	Medchal	20.20	22.20	02.00	BD	11KV Line cut and replaced at Gowdawelly Village	-
5		Medchal	IDA Kistapur	11KV	Medchal	21.10	22.40	01.30	BD	Cloth fallen on the 11KV Line at Vinod Tubes Company	-
6		Thurkapally	Yadaram	11KV	Medchal	19.40	21.00	01.20	BD	No Fault	-
7		Gowdawelly	Ayodhya	11KV	Medchal	16.45	17.55	01.10	BD	11KV Line cut and replaced near SS	-
1		RR E	Yapral	Yapral	11KV	Sainikpuri	20.50	21.30	00.40		11Kv Disks failure at Kalyan Garden (AE/OP)
2	Vinayak Nagar		Tankbund	11KV	Sainikpuri	20.52	21.22	00.30		11Kv Pin Insuletor failure at Sharadha Nagar (AE/OP)	-
1	HYD S	Aliyabad	Shamsheergunj	11KV	III	14.01	15.34	01.33	EL	Tree branches fallen on lines at Goshala	-
2		Attapur	Kishanbagh OH	11KV	III	21.47	23.15	01.28	EL,OL-Bph	Pin Insulator flash over & HT Jumper cut at Pakija Oil Mill	-
3		Miralam	Madina Masjid	11KV	III	21.55	23.40	01.45	EL,OL-Bph	No Visible Fault	-
4		Miralam	Teegala Kunta	11KV	III	22.25	23.50	01.25	EL	Kite Sticks fallen on lines at Jama Masjid	-
5		Kandikal Gate	Patel Nagar	11KV	III	22.55	00.45	01.50	EL,OL	Kite Sticks fallen on lines at Tanaji Nagar	-
6		Jiyaguda	Tappa Chabutra	11KV	IX	22.57	00.07	01.10	EL	Kite Sticks fallen on lines at Tappa Chabutra	-
7		Yakuthpura	Khan Nagar	11KV	VIII	23.00	01.50	02.50	EL	Kite Sticks fallen on lines at Khan Nagar	-
8		Ch' Baradari	Bilal Nagar	11KV	III	23.05	01.50	02.45	EL,OL	Cable fault at Holytown School	-
9		Gunj	Muntaz College	11KV	VIII	23.08	01.03	01.55	EL	Kite Sticks fallen on lines at Arya Samaj	-
10		Panjesha	Metherwadi	11KV	III	23.21	00.43	01.22	EL	Pin Insulator flash over & Kite Sticks fallen on lines at Matherwadi	-
11		Yakuthpura	Murthuza Nagar	11KV	VIII	23.45	01.00	01.15	EL	Kite Sticks fallen on lines at Moula Ka Chilla	-
1	HYD C	Nampally	Bada Masjid	11KV	VII	14.11	15.23	01.12	OL-R&Yph	Conductor snapped at Bazarghat	-
2		Nizam College	Rosary Convent	11KV	I	22.45	23.50	01.05	EL	Bird fault on lines at ACE Coaching Center	-