

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	2	1	2	1	2			
7	RR(E)	168	403									
8	Hyd	194	1044		6		6		6			
	Total	606	3055	1	8	1	8	1	8	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	4	31	4	31	4	31			
3	MDK	107	933		2		2		2			
4	SDPT			3	8	3	8	3	8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	7	42	7	42	7	42	0	0	
	Grand Total	1082	6468	8	50	8	50	8	50	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.12.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Bhongir	Thukkapur	33KV	Bhongir	10:24	11:26	1:02	E/L	33kv Pin Insulator failed near Bachpan school	Thukkapur	No
2		Dirincherla	Mukundapuram	33KV	Huzurnagar	07.00	10.30	03.30	EL/OL	33KV Disc insulator failed	Mukundapuram	No
3		Munagala	Bethavolu	33KV	Huzurnagar	06.00	10.00	04.00	EL/OL	33KV Line snapped	Bethavolu	No
4		K.M.Pally	Neredugomma	33KV	Devarakonda	06.30	08.30	02.00	E/L	B/D due to rain	Neredugomma	No
1	SDPT	Siddipet	Circleoffice	33KV	Siddipet	0:00	11:15	11:15		B/D due to light rain	Circleoffice	No
2		Siddipet	Narsapur	33KV	Siddipet	00.00	14.05	14.05		B/D due to light rain	Narsapur	No
3		Thunikibollaram	Sitharampaly	33KV	Gajwel	00.00	00.09	00.09		B/D due to light rain	Sitharampaly	No
1	RR N	33KV Aliabad	Medchal	33KV	Medchal	1:50	2:30	0:40		Tree fallen on the 33KV Line at Thurkapally	Medchal	Backfeed arranged to 33KV Aliabad feeder from 132KV LGM Pet

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Teegalapally	Karkalpad	11KV	Jadcherla	09.00	10.50	01.50		Bird fallen on the line near Karkalpad (V) Mamidi thota	No
1	NLG	MT.Pally	Mulkalapally	11KV	Bhongir	6:30	10:30	4:00	E/L	11kv Insulator Faill nera Mulakapally Villge	No
2		Y.Gutta	Town	11KV	Bhongir	00.00	02.00	02.00	E/L	11kv Disc Faill Near Yadagiri Gutta Bus Depo	No
3		Mothkur	RWS	11KV	Bhongir	5:00	09.00	04.00	E/L	11kv Disc Faill Near Aroolla well near	No
4		Addagudur	Addagudur	11KV	Bhongir	04.30	08.00	03.30	E/L	SS 2 11kv Insulator Faill Addagudur Villge	No
5		Choutuppal	Thangadapally	11KV	Choutuppal	08.30	13.00	04.30	E/L	11kv Line Snapped at Ramreddy Poltery Fome	No
6		Jammigadda	Estate Feeder	11KV	Suryapet	07.05	08.40	01.35	E/L	11Kv Insulator flashover	No
7		Penpahad	Bakthalapuram	11KV	Suryapet	08.35	11.34	02.59	E/L	11Kv Insulator flashover	No
8		Dirincheria	Chellepally	11KV	Huzurnagar	07.00	10.10	03.10	EL	11KV Line Snapped	No
9		Garidepally	Kalmalcheruvu	11KV	Huzurnagar	05.00	08.30	03.30	EL	11KV Jumper Cut	No
10		Mukundapuram	Kalluru	11KV	Huzurnagar	08.00	11.30	03.30	EL	11KV Line Snapped	No
11		NB Gudem	Redlakunta	11KV	Huzurnagar	06.00	09.45	03.45	EL	11KV Disk Failed	No
12		Amaravaram	Lingagiri	11KV	Huzurnagar	05.00	07.00	02.00	EL	11KV Line Snapped	No
13		Pajjur	Pedda Suraram	11KV	Nalgonda	12.30	01.20	11.10	E/L	11 KV Insulator failed	No
14		Eduloor	Munukuntla	11KV	Nalgonda	11.50	14.20	02.30	E/L	11KV Line jumper cut nearby village	No
15		Eduloor	Parada	11KV	Nalgonda	10.10	12.00	01.50	E/L	11 KV Insulator failed	No
16		Arlagadda Gudem	Suraram	11KV	Nalgonda	11.30	14.30	03.00	E/L	11KV line cut at village end	No
17		Aregudem	Peddakaprthy	11KV	Nalgonda	07.00	10.00	03.00	O/L	HT/LT lines melting	No
18		Arjala Bavi	Marrigudem	11KV	Nalgonda	12.05	13.05	01.00	O/L	Tree on the follow on the Line	No
19		Police Center	Raily Feeder	11KV	Nalgonda	07.20	08.10	00.50	E/L	11KV line cut at village end and 11KV Insulator failed	No
20		Pochampally	Pochampally	11KV	Devarakonda	23.00	09.00	10.00	E/L	11KV Insulator failed	No
21		Laxmidevigudem	Ravulapenta	11KV	Miryalguda	07.00	14.00	07.00	E/L	Jumper cut at Ravulapenta	No
22		Yacharam	Annaram	11KV	Miryalguda	06.00	08.10	02.10	E/L	Tree Fallen in the line	No
23		Avatnhipuram	Rainipalem	11KV	Miryalguda	07.00	09.00	02.00	E/L	Tree Fallen on the line	No
24		V.K.Palem	Thungapadu	11KV	Miryalguda	03.45	14.50	11.05	E/L	11KV line jumper to pole	No
25		Nandipahad	Iyalapuram	11KV	Miryalguda	03.00	11.00	08.00	E/L	Jumper touching to S-ph DTR pole	No
26		Damarcherla	T.v.Gudem	11KV	Miryalguda	01.00	17.10	16.10	E/L	Tree branches fallen on line	No
27		A.D.Pally	Mudimanikyam	11KV	Miryalguda	07.30	15.30	08.00	E/L	Jumper cut at Banjara thanda	No
28		Nidmanoor	Shakapuram	11KV	Miryalguda	07.00	11.30	04.30	E/L	Tree branches fallen on line	No
29		Kothagudem	Kothagudem	11KV	Miryalguda	10.50	14.40	03.50	E/L	Tree branches fallen at Maramma thanda	No
30		V.K.Palem	V K Palem	11KV	Miryalguda	17.25	18.47	01.22	E/L	11KV cable fault near the Rice Mill	No
31		Matoor	Ragadapa	11KV	Miryalguda	13:30	16:50	3:20	E/L	Pole leaned at Ragadapa	No
1	MDK	Alamaipet	Sangupet	11KV	Jogipet	9:36	7:12	2:50		Jumper cut near Sangupet (V)	No
2		Patancheru Town	MIA-I	11KV	Patancheru	02.05	03.15	01.10		11KV Jumper cut at Raju Tools Company	No
1	SDPT	Guggilla	Guggilla	11KV	Husnabad	1:30	10:00	8:30		3PH BD,11KV Insulator failure & rainfall	No
2		Chityal	Chityal Agl	11KV	Husnabad	00.00	08.00	08.00		BD 3PH Due to rainfall	No
3		Komuravelly	Kadavergu	11KV	Husnabad	00.00	13.17	13.17		BD due to rainfall & DTR problem	No
4		Nagapuri	Pothireddypalli	11KV	Husnabad	00.00	08.45	08.45		BD due to rainfall & tree branches	No
5		Komuravelly	Inapur 24 Hrs	11KV	Husnabad	00.00	11.30	11.30		BD Due to tree falling on line	No
6		Pandilla	Pandilla Rural	11KV	Husnabad	01.00	07.00	06.00		BD due to rainfall	No
7		Gandipally	Ramavaram Exp	11KV	Husnabad	00.00	08.10	08.10		BD due to rainfall & tree branches	No
8		Guggilla	Gagillapur	11KV	Husnabad	0:00	14:16	14:16		3PH BD,11KV Insulator failure & conductor snapped	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Madinaguda	Swaranapuri colony	11KV	Kukatpally	18:10	19:50	1:40		11kv AB cable Failure At Swaranapuricolony	No
2		Devarayamjal	Kottapet	11KV	Medchal	00.30	02.00	01.30		Tree fallen on the 11KV Line at Guava Garden, Devarayamjal	No
1	HYD S	Kandikal Gate	Gazi Millath Colony	11KV	Charminar	00.35	05.15	04.40	EL	Kite Stick fault, tree braches fallen on lines & Disc Insulator flash over at Station Road, Suhana Function Hall & Rubi Hotel	No
2		Aliyabad	Sharada College	11KV	Charminar	0:42	2:30	1:48	EL	Kite Stick fallen on lines at Sharada College	No
3		Ch' Baradari	I.T.I Colony	11KV	Charminar	0:45	1:55	1:10	EL	No visible fault due to Rain	No
4		Miralam	Madina Masjid	11KV	Charminar	11:10	12:30	1:20	EL,OL	Cable fault at Hasan Nagar	Arranged B/F on 11KV Hasan Nagar feeder
1	HYD C	Nizam College	Galaxy Hotel	11KV	Saifabad	00.10	02.30	02.20	OL	AB Switch problem at TATA Motors	Arranged B/F on 11KV T.T.D feeder
2		Durga Nagar	Bapu Nagar	11KV	Azamabad	06.05	07.18	01.13	EL,OL-Rph	No visible fault due to Rain	Arranged B/F on 11KV Play Ground fdr