

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		8		8		8			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	9	1	9	1	9	0	0	
	Grand Total	1082	6468	1	12	1	12	1	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 19.12.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kanagal	Kanagal ss	11KV	Nalgonda	05.30	08.50	03.20	E/L	11KV Line cut	-
2		Narsingbatla	Chaulugudem	11KV	Nalgonda	09.00	12.20	03.20	E/L	Insulator failure	-
3		M.R.Gudem	Indus	11KV	Bhongiri	04.00	07.45	03.45	E/L	11KV Disk failure	-
4		Mothkur	Mothkur rural	11KV	Bhongiri	08.30	09.50	01.20	E/L	11KV Insulator insulator	-
5		Dilchinchera	Yellapuram	11KV	Huzurnagar	08.00	11.00	03.00	E/L	11KV Line cut	-
6		Mellacheruvu	Mellacheruvu	11KV	Huzurnagar	14.05	15.20	01.15	E/L	11KV Line snapped	-
7		Laxmidevigudem	Ravulapenta	11KV	Miryalaguda	07.00	09.00	02.00	E/L	Jumper cut	-
8		Yacharam	Annaram	11KV	Miryalaguda	06.00	08.20	02.20	E/L	Insulator failure	-
1	MDK	SRD T-II	No.1	11KV	Sangareddy	20.40	21.40	01.00		B/D due Jumpet cut	-
1	HYD N	I.D.P.L	Shivalayam	11KV	VI	13.35	15.05	01.30	EL,OL-Bph	Cable Fault at ICICI Bank	Arranged B/F on 11KV Bala Nagar fdr
2		Prashanth Nagar	Andhra Jyothi	11KV	VI	17.30	18.45	01.15	EL	Pin Insulator flash over at Rajive Gandhi Nagar	-----
3		H.A.L	Samrat	11KV	VI	22.45	00.05	01.20		AB Cable fault & Line snapped at Shivalayam, Raju Colony	-----

TSSPDCL - LMRC / Corporate office

Date: 19.12.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Shadnagar	Mogiligidda	33KV	Shadnagar	12.00	13.05	01.05		Due to breaker limb problem at 132KV Shadnagar SS	Mogiligidda	Allternate supply arranged from 132KV Srirangapur SS at 13.05 hrs