

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	5	1	5	1	5	0	0	
	Grand Total	1082	6468	1	8	1	8	1	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 20.12.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	RWS	33KV	Gadwal	12.00	13.05	01.05	EL	LA Replacement at Mission Bhageeratha Jurala SS	Gadwal	NO

TSSPDCL - LMRC / Corporate office

Date: 20.12.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Gundrampally	Gundrampally	11KV	Nalgonda	14.15	16.20	02.05	EL	11KV Line insulator failed	-
2		Thatipamula	Thatipamula	11KV	Suryapet	06.52	09.29	02.37	EL	Insulator failed	-
3		Garidepally	L B Nagar	11KV	Huzurnagar	08.05	11.00	02.55	EL	Due to 11Kv jumper cutted	-
4		Pedaveedu	Pedaveedu	11KV	Huzurnagar	09.15	12.10	02.55	EL	Due to 11Kv line cutted	-
5		Nelamarry	Nelamarry	11KV	Huzurnagar	12.30	15.30	03.00	EL	Due to 11Kv line cutted	-
1	RR N	Jeedimetla-IV	Tagoure	11KV	Jeedimetla	06.40	08.30	01.50	EI/OL	11kv line AB Cable failed at opp:Tagoure company	-
1	RR E	NGRI	Kalyanipuri	11KV	Habsiguda	04.55	06.05	01.10		11KV 2Nos Poles damaged near Balaji Temple & 11KV Jumper opened near Balaji Temple	-
1	HYD N	Clock Tower	Station Road	11KV	Sec-Bad	11.58	13.10	01.12	All Indication	RMU Cable fault	Arranged B/F on 11KV Sangeeth & Gurudwara fdrs