

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		4		4		4			
3	MDK	107	933		4		4		4			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	8	0	8	0	8	0	0	
	Grand Total	1082	6468	0	10	0	10	0	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.12.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Mudigonda	Gottimukkala	11KV	Devarakonda	05.00	06.45	01.45	E/L	11KV Insulator failure	-
2		Ghanapuram	Kondapuram	11KV	Devarakonda	15.00	16.30	01.30	E/L	11KV Jumper cut	-
3		SLBC	Kothapally	11KV	Nalgonda	06.06	08.10	02.04	E/L	11KV Jumper cut	-
4		Kalmalacheruvu	Kalmalacheruvu	11KV	Huzurnagar	06.00	08.30	01.30	E/L	11KV Line Snapped	-
1	MDK	Buchinelly	Buchinelly	11KV	Zaheerabad	00.00	03.00	03.00		B/D Due to Jumper Cut	-
2		Tumkunta	Tumkunta	11KV	Zaheerabad	00.00	04.00	04.00		B/D Due to Conductor Snapped	-
3		Gudpally	Gudpally	11KV	Zaheerabad	07.30	09.10	01.40		B/D Due to Jumper Cut	-
4		Nagireddypally	Nagireddypally	11KV	Zaheerabad	07.05	12.00	04.55		B/D Due to Conductor Snapped	-
1	RR N	Kandlakoya	Godrej IDA	11KV	Kukatpally	08.55	10.25	01.30		11KV Pin Insulator failed at Nuziveedu Seeds	-
1	HYD N	MLA Colony	Shopping Complex	11KV	Banjarahills	02.20	04.16	01.56	EL	2No. AB Cable End Kits failed at Plot No.128 A	-