

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>0</b>	



TSSPDCL - LMRC / Corporate office

Date: 26.12.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nemaragomala	Jamelapet	11KV	Bhongir	11:46	13:26	1:40	E/L	11KV Line snpped at Rairavpeta Villge	No
2		Sharjipet	Tangtoor	11KV	Bhongir	12.30	13.00	00.30	E/L	Tree branches fallen at Tangtoor Villge	No
3		Dirincherla	Town-2	11KV	Huzurnagar	10.50	12.10	01.20	OL	Tree fallen on the line	No
4		Ch.Mamidi	Kompally	11KV	Nalgonda	06.30	11.20	04.50	E/L	Inaulator failed	No
5		Kopple	Bheemaram	11KV	Nalgonda	7:50	9:15	1:25	E/L	11KV Jumper cut at Bheemaram (V)	No
1	RR N	Shameerpet	Shameerpet	11KV	Medchal	14:35	15:50	1:15		11KV Line cut at Babaguda Village	No
1	HYD S	Falaknuma	Vattepally	11KV	Charminar	14.10	15.40	01.30	EL,OL-Rph	Conductor snapped at G.S.Darga	No
1	HYD C	Bathakamma Kunta	Saibaba Temple	11KV	Azamabad	23.45	01.26	01.41	OL	Pin Insulator flash over at Andhra Bank	No