

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	1	2	1	2	1	2		2 Nos. 33kv still
2	NLG	144	988		12		12		12			
3	MDK	107	933	2	2	2	2	2	2			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>6</b>	<b>16</b>	<b>4</b>	<b>16</b>	<b>4</b>	<b>16</b>	<b>2</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>6</b>	<b>20</b>	<b>4</b>	<b>20</b>	<b>4</b>	<b>20</b>	<b>2</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 29.12.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Jadcherla	Kollur	11KV	Depally	14.45	15.15	00.30		11KV Wire Cut near Charkonipally Thanda	-
1	NLG	Eduloor	Naragudem	11KV	Nalgonda	13.00	16.00	03.00	E/L	11KV jumper cut	-
2		Turkapally	Hyjalapuram	11KV	Nalgonda	08.30	11.00	02.30	E/L	11KV Insulator failed	-
3		Tripuraram	Tripuraram Indl	11KV	Miryalguda	00.30	06.00	05.30	E/L	Lorry hitting the 11KV pole	
4		Thungathurthy	Banda Ramaam	11KV	Suryapet	10.30	13.00	02.30	E/L	11Kv Insulator flashover	
5		Mukundapuram	Somaram	11KV	Huzurnagar	04.30	07.45	03.15	O/L	Tree brancnch fall on 11Kv line	
6		Mamillagudem	Mothey agl	11KV	Huzurnagar	08.15	11.00	02.45	E/L	11kv jumper cut	
7		Sirikonda	Namavaram	11KV	Huzurnagar	07.30	09.45	02.15	E/L	Bird fall on 11kv line	
8		Bethavolu	Bethavolu	11KV	Huzurnagar	09.00	12.00	03.00	E/L	11Kv line cut	
9		Venkiriyaala	Venkiriyaala	11KV	Bhongir	06.25	07.46	01.16	E/L	Tree Branches Fallen at Line Venkiriyaala Villge	
10		NG.Bandal	Gandamalla	11KV	Bhongir	09.30	12.45	03.15	E/L	11kv Post Of Insulator Fail at Indira nagar Villge Gandamalla	
11		Choutuppal	Ch.Kandukur	11KV	Choutuppal	07.30	09.55	02.25	E/L	100 kva DTR Fail in Chinnakandukur Villge	-
12		Jai.Kesaram	Asonigudem	11KV	Choutuppal	08.05	09.34	01.29	E/L	SS 15 Near Cabul Cut	-
1	MDK	Patancheru town	Town	11KV	Patancheru	17.50	18.40	00.50		BD due to Conductor snapped	-
2		Gundla Machnoor	Arch Pharma	11KV	Jogipet	07.30	11.10	03.40		BD due to 2No,s Insulators failed	-
1	SDPT	Husnabad	Nagapuri	11KV	Husnabad	02.00	08.40	06.40		BD due to Conductor snapped	-
1	RR N	Dppally	AGL Gagillapur	11KV	Jeedimetla	06.00	11.40	05.40	EL	11kv line Cut at Duddigal Chinna cheruvu katta	-
1	RR E	Moula-Ali	HCL	11KV	Sainikpuri	15.46	16.25	00.39		Kite fallen on 11Kv line at Mangapuram Colony (LM Venkatesh)	-
1	HYD C	Public Garden	Nampally Railway Station	11KV	I	02.10	04.05	01.55	EL,OL-Rph	5Way R.M.U fault near Haz House	Arranged B/F on 11KV Gunfoundry fdr
2	HYD S	Kandikal Gate	Patel Nagar	11KV	III	19.20	21.08	01.48	EL	Cable Fault at Uppuguda Railway Station	Arranged B/F on 11KV Gowlipura fdr

TSSPDCL - LMRC / Corporate office

Date: 29.12.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Mathati	33KV	Nagarkurnool	04.56	12.46	07.50	E/L	Line Petroling Done and Tree Cutting	Mathati	-
2		Kothur	Ennar Steel	33KV	Shadnagar	20.05	00.00	03.55		Due to Lorry Accident tobe Tower Near Kurnool Cylinder Company Not Rectified	Ennar Steel	
3		Kothur	Thimmapur	33KV	Shadnagar	20.05	23.25	03.20		Due to Lorry Accident tobe Tower Near Kurnool Cylinder Company	Thimmapur	
4		Kothur	Saint Gobain	33KV	Shadnagar	20.05	00.00	03.55		Due to Lorry Accident tobe Tower Near Kurnool Cylinder Company Not Rectified	Saint Gobain	
1	MDK	Pashamailaram	EPIP	33KV	Sangareddy	16.45	19.15	02.30		BD due to Jumper cut at Excel rubber company	EPIP	-
2		Narayankhed	Shankarampet	33KV	Jogipet	04.20	10.05	05.45		BD due to Jumper cut & Insulator failed	Shankarampet	-