

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360									
7	Hyd	186	1014	1		1		1				
	Total	504	2929	1	2	1	2	1	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		3		3		3			
3	MDK	87	828	1	1	1	1	1	1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	4	1	4	1	4	0	0	
	Grand Total	908	6149	2	6	2	6	2	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.02.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Gaddipaly	Kuthubushapur	11KV	Huzurnagar	14:30	15:30	01.00	E/L	AB switch fault at Kuthubushapur (V)	No
2		Mattapally	Ramachandrapuram	11KV	Huzurnagar	15.00	16.10	01.10	E/L	11KV Jumper failed near Ramachandrapuram (V)	No
3		Munagala	Turkagudem	11KV	Huzurnagar	07.35	10.35	03.00	O/L	DTR failed near Turkagudem (V)	No
1	MDK	NSF	Machavaram	11KV	Medak	07.10	08.40	01.30		Jumper cut	No
1	RR N	Medicity	IDA	11KV	Medchal	0:00	3:00	3:00		11KV UG Cable failed at Gandhi Statue, Ganapur Village	No
2		Athiwelly	Somaram	11KV	Medchal	22.01	23.31	01.30		11KV Pole damaged by Lorry at Somaram X road	No

TSSPDCL - LMRC / Corporate office

Date: 08.02.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	R.C.Puram	Annapurna Foils	33KV	Patancheru	15:50	19:15	3:25		Jumper cut	Annapurna Foils	No
1	HYD N	132KV Jublee Hills	Road No.22	33KV	Kalyan Ngr	03.42	03.50	00.08	OL-Bph	Cable fault at Peddamma Temple		Loads transferred onto 132KV Jublee Hills SS via 33KV Yousufguda feeder