

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360									
7	Hyd	186	1014									
	Total	504	2929	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		2		2		2			
2	NLG	150	948		1		1		1			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	0	3	0	3	0	3	0	0	
	Grand Total	908	6149	0	4	0	4	0	4	0	0	

TSSPDCL - LMRC / Corporate office

Date: 19.02.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Teegalapally	Kakarlaphadu	11KV	Jadcherla	08.00	10.00	02.00		Tree follon the line near Kalarlaphadu	-
2		Midjil	Veljal	11KV	Jadcherla	09.40	11.50	02.10		11kv wire cut near Midjil	-
1	NLG	Pamanagundla	Pamanagundla	11KV	Nalgonda	10.30	12.40	02.10	E/L	11 KV line jumper cut	-
1	RR N	HMT	Ganesh Nagar	11KV	Medchal	15.15	16.15	01.00	BD	100KVA T/F HG Fuse Insulator failed at Cherukupally Colony	-

