

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360		1		1		1			
7	Hyd	186	1014	1		1		1				
	Total	504	2929	1	2	1	2	1	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1		1		1				
2	NLG	150	948		1		1		1			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	1	1	1	1	1	0	0	
	Grand Total	908	6149	2	3	2	3	2	3	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.02.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Arlagaddagudem	Suraram	11KV	Nalgonda	05.20	08.30	03.10	E/L	11 KV Jumper Cut and Insulator Failed at Suraram (V)	-
1	RR N	J D M SS-IV	Tagorea	11KV	Jeedimetla	04.32	05.40	01.08	EL	11kv AB Cable Failure OPP Sub-Station	-
1	RR E	Vasanthapuri	Old Mirzalguda	11KV	Sainikpuri	12.25	13.25	01.00		DTR Iron road fallen 11Kv line at Jeethendra Enclave (L.Insp Venkateshwarulu)	-

TSSPDCL - LMRC / Corporate office

Date: 25.02.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Kollur	33KV	Jadcherla	12.30	14.35	02.05	E/L	Disc Replacement at 132KV Balanagar	Balanagar	-
1	HYD S	220KV Shivrampally	Miralam	33KV	Malakpet	02.25	02.35	00.10	EL,OL,	Cable fault at N.P.A.	220KV Shivrampally	Loads transferred onto 220KV Shivrampally SS via 33KV Ch' Baradari OH feeder