

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		2		2		2			
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360									
7	Hyd	186	1014		1		1		1			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1	2	1	2	1	2			
2	NLG	150	948		2		2		2			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 27.02.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maddur	Raniwatla	11KV	Mahabubnagar	10.30	12.30	02.00		11KV Conductor cut at Raniwatla (Vi)	-
2		Kosgi	Sampally	11KV	Mahabubnagar	10.35	11.55	01.20		11KV Conductor cut Near Sampally Vi)	-
1	NLG	Phanigiri	Anantharam	11KV	Suryapet	07.30	10.00	02.30	E/L	Line Cut	-
2		Shivannagdem	Ramreddy palli	11KV	Devarakonda	14.30	15.30	01.00	E/L	Insulator failure	-
1	RR S	RJNR	Ibrahimbagh	11KV	Military-II	07.22	08.27	01.05	B/D	11KV Line twisted at P&T Colony	-
2		RJNR	Kattedan-I	11KV	Feeder-VI	17.05	18.45	01.40	B/D	CTPT Failed at Tated metal	-
1	RR N	Jeedimetla-I	Maheshwari	11KV	Jeedimetla	17.45	19.45	02.00	EL/OL	11kv line AB Cable Failure near PumpHouse ,Maheshwari	-
1	HYD N	H.A.L	Lokesh Machine	11KV	Bowenpally	02.02	03.12	01.10	EL	Cable fault at Lokesh Machine	Arranged B/F on 11KV T.C Bala Nagar fdr

TSSPDCL - LMRC / Corporate office

Date: 27.02.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effectted	Alternate Supply Arranged
1	MBNR	Marikal	Gunmukla	33KV	Mahabubnagar	12.16	14.25	02.09	E/L	No visible fault Supply Stude OK	Marikal	-