

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360									
7	Hyd	186	1014		1		1		1			
	Total	504	2929	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1		1		1				
2	NLG	150	948		6		6		6			
3	MDK	87	828	2	2	2	2	2	2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	3	8	3	8	3	8	0	0	
	Grand Total	908	6149	3	10	3	10	3	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.01.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Rajapeta	Ranikunta	11kv	Bhongir	08.20	11.00	02.40	EL	11Kv Insulator Failed at Ranikunta Village	-
2		Koppla	BOLLARAM	11kv	Devarakonda	11.30	14.30	03.00	EL	11kv Jumper cutt	-
3		Alingapuram	Chennaipalem	11kv	Huzurnagar	18.00	21.00	03.00	EL	11 kv jumper cutting at Alingapuram village	-
4		BNL Thnada	Vardhapuram	11kv	Huzurnagar	21.35	23.35	02.00	EL	11 kv line snapped at Vardhapuram village	-
5		G.Malkapuram	G.Malkapuram	11kv	Huzurnagar	17.25	18.25	01.00	EL	11 kv jumper cutting at G. malkapuram village	-
6		G.T Giri	Gunjaloor	11kv	Suryapet	07.40	10.20	02.40	EL	Line cut	-
1	MDK	Reddypally	Chippalthurthy	11kv	Siddipet	10.30	14.20	03.50		B/D Due to Jumper Cut	-
2		Burugupally	Burugupally	11kv	Siddipet	16.06	16.30	00.24		B/D Due to Jumper Cut	-
1	RR N	Athiwelly	Gubba	11kv	MDCL	08.15	09.15	01.00		11KV Disc failed at Rekula Bhavi	-
1	HYD S	Ch' Baradari	Bilal Nagar	11kv	Charminar	03.00	04.50	01.50	EL,OL-Rph	HT Line snapped & I/C Jumper cut at Dopasha Darga	

TSSPDCL - LMRC / Corporate office

Date: 06.01.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Oil Seeds	Gadwal	33kv	Gadwal	12.35	14.35	02.00	E/L	Jumpers Open at Beerole SS due to snake Fallen on the Beeroli Line	Gadwal	-
1	MDK	Habsipur	Raghothampally	33kv	Siddipet	06.50	08.30	01.40		B/D Due to Conductor Snapped	Raghothampally	-
2		Habsipur	Raghothampally	33kv	Siddipet	12.30	13.00	00.30		B/D Due to Conductor Snapped	Raghothampally	-