

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360		3		3		3			
7	Hyd	186	1014	1	3	1	3	1	3			
	Total	504	2929	1	7	1	7	1	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		1		1		1			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	0	1	0	1	0	1	0	0	
	Grand Total	908	6149	1	8	1	8	1	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 14.01.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD N	132KV Chilalguda	Clock Tower	NT	Nehru Ngr	01.30	01.40	00.10	EL,OL	Cable fault at Pillar No.22, Gurudwara	132KV Chilalguda	Loads transferred onto 132KV Gunrock SS via 33KV James Street feeder

TSSPDCL - LMRC / Corporate office

Date: 14.01.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Chinthapally	Chinthapally town	11KV	Devarakonda	14.34	17.20	03.00	EL	Insulator fail	-
1	RR N	Chintal	Dwaraka Nagar	11KV	Medchal	16.15	18.30	02.15		11KV Jumper cut and replaced at Madhusudhan Reddy Nagar and Chintal	-
1	RR E	Vasanthapuri	Ganesh Temple	11KV	Sainikpuri	12.24	13.24	01.00		Ground Patrolling Done But No Fault Found (L.Insp Venkateshwarulu)	-
2		AUTONAGAR	HIGHCOURT COLONY	11KV	SAROORNAGAR	16.54	17.45	00.51	OL	LINE PETROLLING NO FAULT FOUND	-
3		BAGATHSINGNAGARM	LINGOJIGUDA	11KV	SAROORNAGAR	13.37	16.09	02.32	EL	OUT GOING END KIT FAIL AT SS LOAD DIVERT TO 11KVSHIVAPURI FEEDER	-
1	HYD C	Asif Nagar	N.S.F Colony	11KV	Mehdipatanam	16.20	17.47	01.27	OL	LT & HT Poles damaged due to Vehicle rammed to Poles at Ice Depot	-
2		Langer House	Prashanth Nagar	11KV	Mehdipatanam	16.58	18.05	01.07	EL,OL-Bph	Kite Sticks fallen on lines at Prashanth Nagar Ground	-
3	HYD S	Salarjung	Purani Haveli	11KV	Charminar	18.25	19.40	01.15	EL	Twisted HT Lines at Miralam Mandi	-