

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407	2		2		2				
6	RR(E)	38	360									
7	Hyd	186	1014		1		1		1			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1		1		1				
2	NLG	150	948		4		4		4			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 20.01.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Eduloor	Kurumarthi	11KV	Nalgonda	08.40	12.35	03.55	EL	11 KV Jumper Cut and Insularo Failed Near Venkat Reddy Well	-
2		Paladugu	Dattappagudem	11KV	Bhongir	02.30	06.30	04.00	EL	11Kv Disk failed at Dattappagudem	-
3		Neradugomu	Kethepally	11KV	Devarakonda	02.15	14.38	02.23	EL	Jumper Cutting	-
4		Alingapuram	Gundlapahad	11KV	Huzurnagar	10.30	14.30	04.00	EL	11 kv jumper cut at Gundlapahad village	-
1	HYD N	Gunrock	Medchal	11KV	VI	14.20	16.06	01.46	EL,OL-Rph	Cable fault at RTC Colony	Arranged B/F on 11KV Kanajiguda fdr

TSSPDCL - LMRC / Corporate office

Date: 20.01.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Maganoor	33KV	Mahabubnagar	19.05	20.50	01.45	O/L	No Fault was Find out	Maganoor	Alternate Supply was arranged from Gudeballore at 20:50Hrs
1	RR N	Medchal	Medchal-II	33KV	Medchal	11.15	14.30	03.15	BD	33KV Conductor Snapped at Outer Ring Road	Medchal-II	-
2		Medchal	Steelmills	33KV	Medchal	11.15	14.30	03.15	BD	33KV Conductor Snapped at Outer Ring Road	Steelmills	-