

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	7	0	7	0	7	0	0	
	Grand Total	1082	6468	0	8	0	8	0	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 01.07.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Koppole (K)	Beemavaram	11KV	Nalgonda	10.00	11.45	01.45	E/L	11 KV Line Jumper Cut	-
2		Biravunibanda	M.G.Kothapally	11KV	Nalgonda	09.00	10.30	01.30	E/L	11 KV Line cut	-
3		Beheelyanaik thanda	Pathathanda	11KV	Huzurnagar	17.30	19.20	01.50	E/L	11 kv line snapped at Pathathanda village	-
4		Raghunadapalem	Gundlapally	11KV	Huzurnagar	19.30	21.30	02.00	E/L	11 kv jumper cut at Gundlapally village	-
5		Kandibanda	Gandinagar thanda	11KV	Huzurnagar	19.13	21.50	02.37	E/L	11 kv snapped at Gandhi nagar thanda	-
6		Ananthagiri	Shantinagar	11KV	Huzurnagar	04.10	06.17	02.07	E/L	11 kv line snapped at Shantingar village	-
1	MDK	Pathur	Shamnapur	11KV	Medak	10.02	12.50	02.48		B/D Due Jumper Cut	-
1	RR E	Rampally Dayara	Vanneguda Indl	11KV	Habsiguda	08.50	10.55	02.05		Bird fallen on 11kv line at Vanneguda Village	-

TSSPDCL - LMRC / Corporate office

Date: 01.07.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
	MBN				NIL							
	NLG				NIL							
	MDK				NIL							
	RRS				NIL							
	RR N				NIL							
	RR E				NIL							
	HYD				NIL							