

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	10	0	10	0	10	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	9	2	9	2	9	0	0	
	Grand Total	1082	6468	2	19	2	19	2	19	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.07.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kudakuda	Iyalapuram	11KV	Suryapet	09.40	10.55	01.15	E/L	Insulator flashover	-
2		Ravulapally	Kukkadam	11KV	Suryapet	07.20	10.30	03.10	E/L	Insulator flashover	-
3		Kandagatla	Gattikal	11KV	Suryapet	09.30	11.50	02.20	E/L	Conductor snapped	-
4		Thurkapally	Ajalapuram	11KV	Nalgonda	07.00	10.00	03.00	E/L	11KV Insulator failure	-
5		Thurkapally	M.Gouraram	11KV	Nalgonda	10.40	13.20	02.40	E/L	11KV Line cut	-
6		Janpahad	Shunyapahad thanda	11KV	Huzurnagar	01.00	03.30	02.30	E/L	11KV Jumper cut	-
7		Palakeedu	Nagireddygudem	11KV	Huzurnagar	05.00	07.30	02.30	E/L	11KV Line snapped	-
1	SDPT	BEJJANKI	KALLEPALLY	11KV	SDPT	13.10	17.00	03.50		INSULATOR BURST	
2		BEGUMPET	BEGUMPET RURAL	11KV	SDPT	14.00	15.00	01.00		JUMPER CUTTING	
1	RR N	Kompally	Jaibheri	11KV	Medchal	01.10	02.26	01.16	BD	11KV Disc Failed at Jaibheri Park	-
2		Kompally	Kompally	11KV	Medchal	12.55	13.45	00.50	BD	11KV AB Cable Failed at Bagireddy Function Hall, Kompally	-
3		Kandlakoya	Saigeetha Asramma	11KV	Medchal	06.16	07.16	01.00	BD	11KV Pin Insulator Failed at Indrasena reddy farm House	-
4		GP Pally	GP Pally	11KV	Medchal	18.20	19.20	01.00	BD	Tree fallen on the 11KV Line at Ayodhya X Road	-
1	RR E	Kushaiguda	Kamala Nagar	11KV	Sainikpuri	02.15	04.20	02.05		11Kv Disk failed at Near HP Petrol Pump (LM Sinivas)	-
2		Vinayak Nagar	RK Nagar	11KV	Sainikpuri	15.08	15.45	00.37		Ground Petrolling done but no Visible fault found due Back Feeding on Shivapuri	-
1	HYD N	Road No.12	Road No.10	11KV	Jubilee Hills	02.50	04.00	01.10	OL	HT Jumper cut at Gowri Shanker Cly	
2	HYD C	Mothi Mahal	Heera Khana	11KV	Mehdipatnam	22.02	23.40	01.38	EL,OL-Bph	Cable fault at Heera Khana	
3		Exhibition	Gandhi Bhavan	11KV	Mehdipatnam	15.15	16.30	01.15	OL-Rph	Cable fault at Board of Intermediate	
4	HYD S	Kulumpura	Rahimpura	11KV	IX	19.40	21.20	01.40	EL,OL-Yph	Cable fault at Mustadanpura (4No. DTR's kept off)	

TSSPDCL - LMRC / Corporate office

Date: 08.07.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	RWS	33kv	Gadwal	05.50	10.55	05.05	E/L	Pin banding work at 132KV SS	RWS	-
2		Shadnagar	Shadnagar	33kv	Mogiligidda	23.00	02.25	03.25	E/L	Bird fallen on the line	Shadnagar	-