

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		11		11		11			
3	MDK	107	933		2		2		2			
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	18	0	18	0	18	0	0	
	Grand Total	1082	6468	0	20	0	20	0	20	0	0	

## TSSPDCL - LMRC / Corporate office

Date: 18.07.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Athmakur(S)	Athmakur Agl	11kv	Suryapet	07.30	10.45	03.15	EL	Disc Flashover	-
2		Palakaveedu	Bothalapalem	11kv	Huzurnagar	11.50	15.00	03.10	EL	Due to 11Kv jumper cutted	-
3		Alingapuram	Raghavapuram	11kv	Huzurnagar	09.58	13.00	03.02	EL	Due to 11kv line cutted	
4		Huzurnagar	Lakkavaram	11kv	Huzurnagar	04.00	06.45	02.45	EL	Due to 11kv line cutted	
5		Timmareddy gudem	Ganapavaram	11kv	Huzurnagar	06.45	10.00	03.15	EL	Due to 11kv line cutted	
6		Pamanagundla	Pittampally	11kv	Nalgonda	08.30	14.20	05.50	EL	11KV line cut near by Kammagudem village	
7		Pamanagundla	Yerasanigudem	11kv	Nalgonda	09.30	14.55	05.25	EL	Tree fallen on 11KV line near Cheruku Narsimha bavi	
8		Arlagaddagudem	Mangalapally	11kv	Nalgonda	06.40	11.40	05.00	EL	11KV Jumper cut	
9		Thipparthi	Gangannapalem	11kv	Nalgonda	14.20	16.40	02.20	EL	11KV line cut near village end	-
10		Kattangur	Dugenelly	11kv	Nalgonda	06.30	08.40	02.10	EL	HT/LT melting nearby village	-
11		Kattangur	Bollepally AGL	11kv	Nalgonda	06.30	09.20	02.50	EL	Heavy gale and wind	-
1	MDK	Kothapally	Kothapally	11kv	Medak	08.30	10.20	01.50		B/D Due to Jumper Cut at Petrol Pump.	-
2		Burugupally	Yelupugonda	11kv	Medak	11.20	14.16	02.56		B/D Due to Insulator Failure	-
1	SDPT	Potharam	Potharam Rural	11kv	Husnabad	08.45	09.30	00.45		BD LINE FAULT	
2		Gurjakunta	Vechareni	11kv	Husnabad	07.45	09.30	01.45		BD INSULATOR FAILURE	
3		Mustyal	Mustyal	11kv	Husnabad	08.15	09.20	01.05		BD INSULATOR FAILURE	
4		Mustyal	Chuchanakota	11kv	Husnabad	08.20	09.20	01.00		BD INSULATOR FAILURE	
5		Komuravelly	Kistampet	11kv	Husnabad	09.40	10.15	00.35		CONDUCTOR SNAPPED	
1	RR E	Balaji nagar	Mahankali	11kv	Keesara	11.45	13.30	01.45		Braker Machanical problem in ss yard	-
1	HYD C	Amberpet	Play Ground	11kv	Azamabad	21.55	23.03	01.08	EL	Insulator flash over at Ganga Golden Towers	

TSSPDCL - LMRC / Corporate office

Date: 18.07.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	mbnr					NIL						-
2	nlg					NIL						-
3	mdk					NIL						-
4	sdpt					NIL						-
5	RR S					NIL						-
6	RR N					NIL						-
7	RR E					NIL						-
8	HYD					NIL						-