

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1	3	1	3	1	3			
	Total	606	3055	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	1	1	1	1	1			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	1	1	1	1	1	0	0	
	Grand Total	1082	6468	2	5	2	5	2	5	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.07.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Mattampally	Huzurnagar	33KV	Huzurnagar	13:30	13:40	0:10	E/L	Jumper cut	Huzurnagar	No
1	HYD N	132KV Madhapur	Deva Bhoomi	33KV	Kalyan Ngr	05.00	07.35	02.35	EL,OL	Cable damaged by TCR opp.Soft Sole Company	Deva Bhoomi	No

TSSPDCL - LMRC / Corporate office

Date: 25.07.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Narketpally	B.Vellemla AGL	11KV	Nalgonda	12:40	14:20	1:40	E/L	11KV Line Jumper Cut	No
1	RR N	Nuthankal	Bharathi	11KV	Medchal	15:42	17:10	1:28		HG Fuse failure	No
1	HYD N	Erramanzil	Durga Nagar	11KV	Erragadda	22.10	23.15	01.05	EL	No Visible Fault	No
1	HYD S	Salarjung	Madina	11KV	Charminar	20.24	22.30	02.06	EL	Insulator flash over Opp. DE/Office	No
2		Salarjung	Madina	11KV	Charminar	22:47	23:55	1:08	EL	No Visible Fault	No