

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		5		5		5			
3	MDK	107	933	2	3	2	3	2	3			
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 30.07.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Palakaveedu	Nagireddigudam	11KV	Huzurnagar	10.40	12.55	02.15	E/L	11Kv insulator failure	-
2		Mukundapuram	Somaram	11KV	Huzurnagar	18.05	19.05	01.00	E/L	11kv line snapped	-
3		Urulugonda	Thummagudem	11KV	Huzurnagar	03.45	06.00	02.15	E/L	11kv line cut	-
4		Indugula	Indugula town	11KV	Nalgonda	08.15	11.35	03.20	E/L	11KV jumper cut	-
5		Mamidala	Aregudem	11KV	Nalgonda	07.05	09.37	02.32	E/L	11KV insulator failed	-
1	MDK	CHERYAL	DVR	11KV	Sangareddy	14.45	15.45	01.00		B/D DUE TO TREE BRANCHES FALLEN ON LINE AT MAMIDIPALLY ROAD	-
2		Sardhana	Balanagar	11KV	Medak	10.55	12.25	01.30		B/D DUE TO JUMPER CUT	-
3		Rangampet	Papannapet Agl	11KV	Medak	09.10	15.00	05.50		B/D DUE TO CONDUCTOR SNAPPED	-
1	SDPT	Mustyal	Chuchanakota	11KV	SDPT	18.30	19.30	01.00		BD DUE TO TREE BRANCES FALLEN ON LINE	
2		Bekkal	Kutigal	11KV	SDPT	15.00	16.00	01.00		BD DUE PTR HG FUSE FAILURE	
1	RR N	Athiwelly	SPIC	11KV	Medchal	05.05	06.10	01.05		11KV Jumper Cut at Rekula Bhavi	-
1	RR E	NGRI	Scientist Colony	11KV	Habsiguda	02.40	03.40	01.00		11KV End kit Cable failed at Habsiguda Cross Road	-

TSSPDCL - LMRC / Corporate office

Date: 30.07.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Gummadidala	Dundigal	33KV	Patancheru	16.05	20.00	03.55		BD due to Conductor snapped	Dundigal	-
2		Minpur	Narsingi	33KV	Medak	00.00	14.05	14.05		BD due to Jumper cut	Narsingi	-
1	RR N	Jeeditmetla ss II	Apuroopa colony	33KV	Medchal	03.15	04.10	00.55	EL/OL	11kv jumper touched the channal at Apuroopacolony Kalyana mandapam	Apuroopa colony	-