

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	1	6	1	6	1	6			
6	RR(N)	54	550		15		15		15			
7	RR(E)	168	403		24		24		24			
8	Hyd	194	1044		27		27		27			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>72</b>	<b>1</b>	<b>72</b>	<b>1</b>	<b>72</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	2	4	2	4	2			
2	NLG	144	988	5	61	5	61	5	61			
3	MDK	107	933	2	12	2	12	2	12			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>11</b>	<b>75</b>	<b>11</b>	<b>75</b>	<b>11</b>	<b>75</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>12</b>	<b>147</b>	<b>12</b>	<b>147</b>	<b>12</b>	<b>147</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 07.06.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Nandinne	33KV	Gadwal	00.05	08.35	08.30	E/L	Insulator Failed and Alternate Supply Taken to 33KV Alwalad Feeder at 8:35Hrs	Gadwal	-
2		Wanaparthy	Narsaipally	33KV	Wanaparthy	00.20	01.55	01.35	E/L	AB Switch open at Niranjanreddy Thota Supply Stud Ok	Wanaparthy	-
3		Wanaparthy	Solipur	33KV	Wanaparthy	03.55	06.30	02.35	E/L	33Kv Insulator Replacement Chinnamandaddi Thanda	Wanaparthy	-
4		Nagarkurnool	Telkapally	33KV	Nagarkurnool	08.15	11.30	03.15	E/L	LA Blast in 132KV SS	Nagarkurnool	-
1	NLG	Suryapet	Chandupatla	33KV	Huzurnagar	20.20	11.30	15.20	EL/OL	33 kv Disk failed at Chanduptal village	Suryapet	-
2		Kolanpaka	Sharajipet	33KV	Bhongir	00.00	06.25	06.25	EL	No fault due to heavy rain & wind	Kolanpaka	-
3		Ramannapet	Yennaram	33KV	Bhongir	01.10	12.00	10.50	EL	pole no 13 Insulater failed	Ramannapet	-
4		Ramannapet	Voligonda	33KV	Bhongir	04.00	12.10	08.10	EL	pole no 115 Insulater failed	Ramannapet	-
5		Marrigudam	Shivanagudam	33KV	Devarakonda	04.48	06.20	06.00	EL/OL	Tree Follan On The Line	Marrigudam	-
1	MDK	Chegunta	Yeludurthy	33KV	Toopran	00.00	06.00	06.00		B/D Due to Insulator failure	Chegunta	-
2		Jogipet	Laxmi sagar	33KV	Jogipet	02.35	09.40	07.05		B/D Due to Insulator failure	Jogipet	-
1	RR S	220kv Shivaram pally	33kv NPA	33KV	RJNR	00.30	05.05	04.35	B/D	33kv Insulator Failed at aramghar x road		

TSSPDCL - LMRC / Corporate office

Date: 07.06.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Teegalapally	Teegalapally	11KV	Jadcherla	11.48	13.10	01.22		B.D.11 KV Insulator failure Near Teegalapally( Vi).	-
2		Kothamolgara	Kothamolgara	11KV	Jadcherla	02.55	07.40	04.45		Tree follen On The 11 kv Line Near Kappeta( Vi).	-
1	NLG	Thungathurthy	Ganugubanda	11KV	Suryapet	13.50	16.30	02.40	EL	Insulator failed	-
2		Keethavarigudem	Laxmipuram	11KV	Huzurnagar	13.30	17.15	03.45	EL	11 kv line snapped at Laxipuram village	-
3		N B Gudem	Redlakunta	11KV	Huzurnagar	00.00	09.30	9:30	EL	11 KV line snapped at Redlakunta village	-
4		Pullemla	Bandapalem	11KV	Nalgonda	06.00	08.00	02.00	E/L	Heavy rain and wind	-
5		Gundrampally	Gundrampally	11KV	Nalgonda	02.00	03.10	01.10	E/L	Heavy rain and wind	-
6		Narsingbatla	Kuturgudem	11KV	Nalgonda	07.00	08.25	01.25	E/L	11 KV Jumper Cut	-
7		Narsingbatla	Chennugudem	11KV	Nalgonda	08.00	09.10	01.10	E/L	Tree fallen on line	-
8		Thoragal	Telakantigudem	11KV	Nalgonda	06.30	08.00	01.30	E/L	11 KV Insulator Failed	-
9		Kesharajupally	Mahilapanganam	11KV	Nalgonda	02.00	03.20	01.20	E/L	Heavy rain and wind	-
10		Turkapally	Kachalapuram	11KV	Nalgonda	06.00	08.00	02.00	E/L	11 KV Jumper Cut	-
11		Aregudem	Ch.Kaparthi	11KV	Nalgonda	03.00	04.30	01.30	E/L	11KV Line Cut	-
12		Narketpally	M.Yedavelly	11KV	Nalgonda	12.26	13.10	00.44	E/L	11 KV Jumper Cut	-
13		Pamanagundla	Ismailpally	11KV	Nalgonda	06.00	07.30	01.30	E/L	11 KV Insulator Failed	-
14		Kethepally	Kasanagode	11KV	Nalgonda	05.40	06.30	00.50	E/L	Heavy rain and wind	-
15		Chinthapally	Power Gird	11KV	Devarakonda	01.35	12.30	10.55	E/L	11 kv Insulator failed	-
16		Chinthapally	Rayanigudam	11KV	Devarakonda	01.40	10.20	08.40	E/L	Tree Follan& Conductor Sanpped	-
17		Chinthapally	Varakala	11KV	Devarakonda	02.00	07.10	05.10	E/L	Tree Follan& Conductor Sanpped	-
18		Chinthapally	Vinjamoor	11KV	Devarakonda	02.00	07.10	05.10	E/L	Tree Follan& Conductor Sanpped	-
19		Chinthapally	H.M.pally	11KV	Devarakonda	02.00	10.30	08.30	E/L	1 No Insulator Failed	-
20		Chinthapally	Nasarlapally	11KV	Devarakonda	08.40	10.20	01.40	E/L	Tree Follan	-
21		Chinthapally	Chinthapally	11KV	Devarakonda	02.30	08.00	05.30	E/L	2 Nos Disc & 1 No Insulator failed	-
22		Madhanapur	Mall	11KV	Devarakonda	02.00	08.30	06.30	E/L	2 Nos Discs failed	-
23		Madhanapur	Madhanapur	11KV	Devarakonda	02.00	10.00	08.00	E/L	Insulator Failed & Conductor Sanpped	-
24		Madhanapur	Kurmed	11KV	Devarakonda	02.00	16.00	14.00	E/L	11 KV Disc & 11 KV Insulator Failed	-
25		Teededu	K.Gowraram	11KV	Devarakonda	02.00	13.40	11.40	E/L	Tree Follan& Conductor Sanpped	-
26		Nampally	Mandhapur	11KV	Devarakonda	04.00	06.00	02.00	E/L	Wind & Gell	-
27		Nampally	Nampally Townen	11KV	Devarakonda	02.00	06.40	04.40	E/L	11 kv Insulator failed	-
28		Nampally	M.R.pally	11KV	Devarakonda	02.00	04.00	02.00	E/L	Wind & Gell	-
29		Nampally	Peddapuram	11KV	Devarakonda	02.00	04.00	02.00	E/L	Wind & Gell	-
30		Marrigudam	Y.G.pally	11KV	Devarakonda	01.00	11.00	10.00	E/L	DTR Falied at Ajalapuram	-
31		Marrigudam	Vattipally	11KV	Devarakonda	01.00	12.00	11.00	E/L	11 KV Disc & 11 KV Insulator Failed	-
32		Marrigudam	Kondur	11KV	Devarakonda	01.00	12.15	11.15	E/L	3-Ph 25Kva Failed SS-01,Kondur	-
33		Chandhampeta	Mudidhandla	11KV	Devarakonda	06.00	15.10	09.10	E/L	Jumper Cut & 11 Kv insulator Failed	-
34		K.M.Pally	Chennaram	11KV	Devarakonda	01.30	07.50	06.20	E/L	Tree Follan& Conductor Sanpped	-
35		Singarajupally	Veeraboinapally	11KV	Devarakonda	03.00	09.00	06.00	E/L	Conductor sanpped	-
36		Dindi	Dindi townen	11KV	Devarakonda	01.00	08.30	07.30	E/L	11 Kv Disc failed	-
37		Dugalya	Thirumalagiri	11KV	Devarakonda	01.00	10.00	09.00	E/L	Tree Follen & Conductor sanpped	-
38		Addagudur	Addagudur	11KV	Bhongir	00.00	10.30	10.30	EL	due to heavy rain & wind 11kv Insulator failed at SS 1 Govindhapur	-
39		Anantharam	Hanmapur	11KV	Bhongir	06.00	10.50	04.50	EL	11kv Disc failed near Hanmapur(v)	-
40		Mt pally	Dathaipally	11KV	Bhongir	21.35	07.00	09.30	OL/EL	due to heavy rain & wind Disc failed at Dathipally (v)	-
41		Chanduplta	Chanduptla	11KV	Bhongir	05.40	10.50	05.10	EL	pin Insulator failed at Co-operative Bank near in Chanduptla(v)	-
42		Bollepally	Surepally	11KV	Bhongir	19.30	11.30	16.00	EL	Insulator failed near Mudaravath sacru well	-
43		NG Bandal	Konapur	11KV	Bhongir	23.20	10.00	11.20	EL	Insulater failed at konapur (v)	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
44		Bibinagar	Gurraladandi	11KV	Bhongir	09.36	10.40	04.00	EL	poles Damaged Alternate supply arranged	-	
45		Bibinagar	Ragavapur	11KV	Bhongir	04.48	10.48	06.00	EL	poles Damaged	-	
46		Rajapet	Narsapur Agl	11KV	Bhongir	06.00	09.10	03.10	EL	due to heavy rain & wind 11kv line snapped near Milk center Chairman home at Rajapat (v)	-	
47		Rajapet	Pamukunta	11KV	Bhongir	06.00	13.30	07.30	EL	11 kv pole & 25 kv DTR damaged	-	
48		Rajapet	renikunta	11KV	Bhongir	06.00	11.10	05.10	EL	11kv Insulator & Disc insulator failed at near mullagudem(v)	-	
49		Alair	Ikkurthi	11KV	Bhongir	00.00	14.00	14.00	EL	11kv pin Insulator pin Binding failed & 2 Nos Poles damaged at JMJ School	-	
50		Bondugula	Parpally	11KV	Bhongir	22.00	18.30	20.30	EL	pin Insulator failed	-	
51		Bondugula	Bondugula	11KV	Bhongir	22.00	18.30	20.30	EL	pole Damaged	-	
52		Bondugula	Godumakunt	11KV	Bhongir	22.00	09.00	11.00	EL	Disc failed at godmakunta (v)	-	
53		Ramannapet	IND	11KV	Bhongir	01.30	08.20	05.50	EL	Tree branches fallen on 11kv line	-	
54		Choutuppal	IND	11KV	Bhongir	00.00	06.50	05.20	EL	No fault due to heavy rain & wind	-	
55		Choutuppal	Choutuppal	11KV	Bhongir	06.00	06.00	08.00	EL	No fault due to heavy rain & wind	-	
56		Malakapur	Thuparan pet AGL	11KV	Bhongir	23.30	13.35	14.45		No fault due to heavy rain & wind	-	
57		Malakapur	Thuparan pet Indu	11KV	Bhongir	23.30	13.35	14.45		CTPT set failed at Ashook Einganaring Collge	-	
58		Juloor	Kapraipally	11KV	Bhongir	06.00	17.15	12.15		11kv 3no's Insulators failed near samaka saraka	-	
59		Juloor	Peddagudem	11KV	Bhongir	06.00	16.50	10.50		11kv Insulator failed near pirula well in peddagem	-	
60		Voligonda	Dasireedy gudem	11KV	Bhongir	17.35	19.10	08.24		Pole's Damaged	-	
61		Voligonda	Nagaram	11KV	Bhongir	17.35	16.00	22.25		Pole's Damaged	-	
1		MDK	Dundigal	Annaram	11KV	Sangareddy	02.00	07.05	05.05		B/D Due to tree branch fallen on the line	-
2			Bonthapally	Veerabhadra	11KV	Sangareddy	04.00	07.00	03.00		B/D Due to Insulator failure	-
3			SANGAREDDY-II	kalabgur	11KV	Sangareddy	02.50	04.40	01.50		B/D Due to Jumper Cut	-
4	FASALWADI		MNR	11KV	Sangareddy	12.05	15.30	03.25		B/D Due to Jumper Cut	-	
5	KONDAPUR		THOGARPALLY	11KV	Sangareddy	07.35	10.40	03.05		B/D Due to Insulator failure	-	
6	CHERYAL		CHERYAL	11KV	Sangareddy	01.00	02.30	01.30		B/D Due to Jumper Cut	-	
7	CHERYAL		INDRAKARAM	11KV	Sangareddy	01.00	06.30	05.30		B/D Due to Jumper Cut	-	
8	CHERYAL		KALIVEMULA	11KV	Sangareddy	07.00	08.30	01.30		B/D Due to Insulator failure	-	
9	CHERYAL		KALIVEMULA	11KV	Sangareddy	14.30	16.55	02.25		B/D Due to Jumper Cut	-	
10	MUNIPALLY		KAMMAMPALLY	11KV	Sangareddy	08.30	13.30	05.00		B/D Due to Conductor Snapped	-	
11	CHERYAL		DULCHAND	11KV	Sangareddy	01.00	08.40	07.40		B/D Due to Insulator failure	-	
12	CHERYAL		MYK	11KV	Sangareddy	01.00	11.50	10.50		B/D Due to Conductor Snapped and Due to Insulator Faliure	-	
1	RRS	APPA	Himayathsagar	11KV	RJNR	01.45	02.45	01.00	B/D	11KV Insulator failed at Kalimandir temple	-	
2		NPA	Raghavendracolony	11KV	RJNR	01.40	02.50	01.10	B/D	11KV Insulator failed at Javed bai company	-	
3		Kattedan-II	Nethajinagar	11KV	RJNR	01.10	02.40	01.30	B/D	No visible fault Due to rain	-	
4		MD Pally	Brundavan colony	11KV	RJNR	02.20	06.00	03.40	B/D	11kv cable limbu Cut Replaced at Brundavan colony X Road	-	
5		MD Pally	Laxmiguda	11KV	RJNR	02.30	06.30	04.00	B/D	11kv insulator Failed and Jumper cut Touching To Channel at Laxmiguda Road	-	
6		Mathrusrinagar	Kalyan Garden	11KV	GCB	01.45	02.45	01.00	B/D	11KV Line AB Switch Opened at Sai Ranga Theatre. 11KV AB Switch Sparked at Sub-Station.	-	
1		Madinaguda	HMT	11KV	Kukatpally	00.39	02.25	01.46	EL	11kv line PinInsulater Failure at Stalien Colony	-	
2		Madinaguda	Video Colony	11KV	Kukatpally	01.07	03.47	02.40	EL	11kv Disk failure at Rinway bar & Restarent, Miyapur	-	
3		Hudatruckpark	Sri sai nagar	11KV	Kukatpally	01.10	02.40	01.30	EL&OL	11kv line Endkit failure at Asian Book House, Sai baba Nagar	-	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
4	RRN	JDMSS-I	CS Wires	11KV	Jeedimetla	00.46	07.07	06.21	EL	11kv line AB Cable failure at CS Wires Company	-	
5		JDMSS-I	Raghava	11KV	Jeedimetla	01.38	05.15	03.37	EL/OL	11kv line AB Cable failure at SD Rubbar Company , Phase-I	-	
6		JDMSS-IV	Axies	11KV	Jeedimetla	03.41	09.50	06.09	EL	11kv line Endkit & CTPT Failure at Shushil plastic Company , Gappala Basthi	-	
7		JDMSS-I	Sudharshan Drugs	11KV	Jeedimetla	05.29	11.03	05.34	EL/OL	11kv line AB Cable failure at Near Sub-station	-	
8		Subash Nagar	Jairam Nagar	11KV	Medchal	01.30	03.45	02.15		Tree Fallen on 11KV Line India Petrol bunk,Jairam Nagar	-	
9		Kompally	Canteenpark	11KV	Medchal	02.28	03.38	01.10		11KV AB cable Failed at KVR Garden	-	
10		HMT	Ganesh Nagar	11KV	Medchal	02.45	04.10	01.25		11KV HG Fuse Insulator Failed at Cherukupally Colony	-	
11		HMT	Manikya Nagar	11KV	Medchal	03.50	05.10	01.20		Tree fallen on the 11KV Line at Indrasingh Nagar	-	
12		Aliabad	LGM Pet	11KV	Medchal	02.00	03.50	01.50		11KV Pin Insulator failed at Kashawada	-	
13		Bommarajpet	Ponnal	11KV	Medchal	02.00	03.40	01.40		11KV Pin Insulator Failed at Bommana Cheruvu,Ponnal	-	
14		Nuthankal	Oystar	11KV	Medchal	07.48	08.40	00.52		Tree fallen on the 11KV Line at Pragnapur Road	-	
15		Bandamadaram	Barmajiguda	11KV	Medchal	05.30	06.40	01.10		Tree fallen on the 11KV Line at Madhura water Plant	-	
1		RR East	Moula ali	Kailasgiri	11KV	Sainikpuri	23.41	02.20	02.39		Tree fallen on 11Kv line at Kaliasgiri (AE)	-
2			Moula ali	Moula ali	11KV	Sainikpuri	23.41	03.30	03.49		Tree fallen on 11Kv line at Kaliasgiri (AE)	-
3			Yapral	Tulasi Garden	11KV	Sainikpuri	22.36	23.36	01.00		Tree fallen on 11Kv line at Jupally Homes (AE)	-
4	Yapral		Tulasi Garden	11KV	Sainikpuri	01.30	03.30	02.00		Tree branches fallen on 11kv line at Sompal Thota (AE/OP)	-	
5	Cherlapally-IV		BN Reddy Nagar	11KV	Sainikpuri	01.30	03.00	01.30		11Kv Cable failure at BN Reddy Nagar back side (AE/OP/Cherlapally-I)	-	
6	VK Nagar		Devi Nagar	11KV	Sainikpuri	07.40	08.30	00.50		Tree branches fallen on 11Kv line at Near Savithri DTR New Vidya Nagar (AE/OP/VK Nagar)	-	
7	Nacharam		Nile	11KV	Habsiguda	23.47	00.58	01.11		Line patrolling but no visible fault due to heavy rain and gale	-	
8	Nacharam		Chandamama	11KV	Habsiguda	00.30	01.50	01.20		Line patrolling but no visible fault due to heavy rain and gale	-	
9	FRUITMARKET		SHIVALAYAM	11KV	Saroor nagar	08.20	09.40	01.20	EL/OL	11KV LINE PERLLING NO FALT	-	
10	BANDLAGUDA		VAMBAYCOLONY	11KV	Saroor nagar	23.48	07.09	07.21	EL/OL	2 NOS 11KV PIN INSULATER FAIL AT GOVARAMENT SCHOOL	-	
11	BANDLAGUDA		CHANIKYAPURI	11KV	Saroor nagar	01.35	02.55	01.20	EL/OL	11KV DISK FAIL AT SAI NAGAR ROAD NO 4	-	
12	RAJIVSWAGRU		VISHALANDRA	11KV	Saroor nagar	00.32	02.47	01.15	OL	11KV LINE PERLLING NO FALT	-	
13	RAJIVSWAGRU		JAIPURICOLONY	11KV	Saroor nagar	00.22	05.04	04.52	EL/OL	COCOKNET BRACHANS FALL ON 11KV LINE AT JAIPURICOLONY	-	
14	TATTIANNARAM		TATTIANNARAM	11KV	Saroor nagar	02.00	04.34	02.34	EL	11KV LINE PERLLING NO FALT	-	
15	TATTIANNARAM		INDUARYAN APPT	11KV	Saroor nagar	02.00	03.32	01.32	EL	11KV LINE PERLLING NO FALT	-	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
16		MOTHER DAIRY	GANESH NAGAR	11KV	Saroor nagar	00.10	07.20	07.10	EL	2 NOS 11KV INSULATER FAIL AT HANUMAN TEMPLE	-
17		PEDDAMBERPET	KOHEDA	11KV	Saroor nagar	03.00	05.00	02.00	EL	11KV LINE PERLLING NO FALT	-
18		Saketh	Dammaiguda	11KV	Keesara	00.05	03.00	02.55		Line patrolling but no visible fault	-
19		Yadgarpally	Thimmaipally	11KV	Keesara	22.30	02.50	04.20		Tree fallen on 11kv line near Damar Company at Thimmaipally	-
20		Aushapur	NFC Nagar	11KV	Keesara	23.30	03.30	04.00		11KV 2Nos Polymer disc failed at SS Yard nad NFC Nagar	-
21		Aushapur	Sandupatlaguda	11KV	Keesara	23.30	04.30	05.00		11KV Nos Pin Insulator failed and 1No Disc failed at Kothaguda Road	-
22		Narapally	Prathap Singaram	11KV	Keesara	00.40	02.05	01.25		Tree branches fallen on 11kv line at Tirumala Nagar	-
23		Narapally	Narapally	11KV	Keesara	23.55	01.55	02.00		Line patrolling but no visible fault	-
24	Chakripuram	Ayyappa	11KV	Keesara	03.25	07.30	04.05		11KV Pin Insulator failed at Bhavani Nagar	-	
1	HYD N	Vasanthapuri	Siripuri Colony	11KV	Sec-Bad	00.00	02.38	02.38	EL,OL	No Visible Fault ( Due to Rain )	Arranged B/F on 11KV Lalapet fdr
2		I.I.C.T	Deccan	11KV	Sec-Bad	00.10	02.30	02.20	EL	Tree fallen on lines (4No DTR's Kept off)	Arranged B/F on 11KV Solex feeder
3		Road No.2	E-Seva	11KV	Banjarahills	00.12	01.45	01.33	EL	No Visible Fault ( Due to Rain )	-
4		Clock Tower	St.Marry's	11KV	Sec-Bad	00.15	04.30	04.15	EL	No Visible Fault ( Due to Rain )	-
5		Nehru Nagar	Teachers Colony	11KV	Sec-Bad	00.20	01.38	01.18	EL	No Visible Fault ( Due to Rain )	-
6		Marredpally	Railway Colony	11KV	Sec-Bad	00.20	01.38	01.18	EL	No Visible Fault ( Due to Rain )	-
7		Bowenpally	Plassy Line	11KV	Bowenpally	00.30	03.30	03.00	EL	Disc Insulator flash over at Check Post	-
8		Addagutta	Shanthy Nikethan	11KV	Sec-Bad	00.58	02.40	01.42	EL	No Visible Fault ( Due to Rain )	-
9		Yellareddyguda	Shalivahana Nagar	11KV	Banjarahills	01.30	03.05	01.35	EL	Insulator flash over at Law College	-
10		Yellareddyguda	Akber Form	11KV	Banjarahills	01.32	03.20	01.48	EL	Tree branches fallen on lines at Akber Form	-
11		Addagutta	Tagore Home	11KV	Sec-Bad	01.40	04.05	02.25	EL,OL-Bph	No Visible Fault ( Due to Rain )	Arranged B/F on 11KV Addagutta fdr
12		H.A.L	Samrat	11KV	Bowenpally	01.48	03.20	01.32	EL	No Visible Fault ( Due to Rain )	-
13		R.P.Nilayam	Alwal	11KV	Bowenpally	01.55	04.05	02.10	EL	Tree fallen on lines at Alwal Mandapam	-
14		Marredpally	Ramser Café	11KV	Sec-Bad	02.10	03.20	01.10	EL	Tree branches fallen on lines at Ramser Café	-
15		Srinagar Colony	Kamma Sangam	11KV	Banjarahills	02.10	04.25	02.15	EL,OL-Rph	Cable End Kit failed & Insulator flash over at Naga	-
16		Nehru Nagar	Contonment	11KV	Sec-Bad	03.33	04.45	01.12	EL,OL-Bph	DTR fault at Tadi Shop	-
17		Vasanthapuri	Sheshapadu	11KV	Sec-Bad	06.18	08.26	02.08	OL	No Visible Fault ( Due to Rain )	-
18		LV Prasad Marg	Gymkhana Club	11KV	Banjarahills	07.26	08.40	01.14	All Indication	No Visible Fault ( Due to Rain )	-
19	LV Prasad Marg	Annapurna	11KV	Banjarahills	13.30	14.35	01.05	All Indication	HT Jumper cut at Annapurna Main Gate	-	
20	HYD S	Moosarambagh	Sripuram Colony	11KV	Asmangadh	00.15	02.35	02.20	OL	Jumper cut at Arora College	-
21		Teegalaguda	Saleem Nagar Milk B	11KV	Asmangadh	00.56	02.12	01.16	EL-Yph	Cable top Jumper touching to DTR at Srinivasa K	-
22		Salarjung	Darulshifa	11KV	Charminar	03.20	04.40	01.20	EL,OL	AB Cable fault at Ground PT	-
23		Moosarambagh	Moosarambagh	11KV	Asmangadh	08.23	09.40	01.17	EL,OL-Rph	HT Line snapped at Hegde Nursing Home	-
24	HYD C	I.T.I Mallepally	Indira Nagar	11KV	Mehdipatanam	00.33	01.40	01.07	EL,OL	No Visible Fault ( Due to Rain )	-
25		Bathkamma Kunta	Saibaba Temple	11KV	Azamabad	01.10	03.48	02.38	OL-Rph	Tree branches fallen on lines at Ayyappa Temple	Arranged B/F on 11KV C.E.Colony fdr
26		Amberpet	Golnaka	11KV	Azamabad	01.35	02.50	01.15	EL	HT Jumper cut at Maruthi Nagar	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
27		Vittalwadi	Kamineni Hospital	11KV	Saifabad	02.45	03.58	01.13	All Indication	No Visible Fault ( Due to Rain )	Arranged B/F on 11KV Taj Mahal feeder