

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044	2	1	2	1	2	1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1				1		1 No. 33KV Still
2	NLG	144	988		9		9		9			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>10</b>	<b>1</b>	<b>10</b>	<b>0</b>	<b>10</b>	<b>1</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>15</b>	<b>4</b>	<b>15</b>	<b>3</b>	<b>15</b>	<b>1</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 09.06.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Mogalmadka	33KV	Mahabubnagar	16.55	18.30	01.35		Due to rain	Mogalmadka	At 18:30 hrs. Alternate Supply Arranged from 33KV Kankurthy
1	RR N	132KV Malkaram	Ratnalayam	33KV	Medchal	4:56	9:20	4:24		33KV Pin insulator failed at Thumkunta	Ratnalayam	No
1	HYD N	132KV Madhapur - Deva Bhoomi-III	Madhapur-(PTR-II)	33KV	Kalyan Nagar	11.00	18.35	07.35	EL,OL-Rph	Cable fault	Madhapur-(PTR-II)	At 11:05 hrs. Alternative supply arranged from 132KV Madhapur - Madhapur - 1
2		132KV Gunrock - Airport	Thirumalagiri	33KV	Nehru Nagar	12:10	6:48	18:38	EL,OL-Bph	Cable damaged	Thirumalagiri	At 12:12 hrs. Loads transferred onto 132KV Gunrock - Macha Bollarum

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kodur	Kommala	11KV	Suryapet	13:15	14:30	1:15	E/L	11KV Insulator failed	No
2		Mattampally	Choutupally	11KV	Huzurnagar	03.30	05.40	02.10	E/L	11KV jumper cut	No
3		Gudimalkapuram	Chintalapalem	11KV	Huzurnagar	03.00	09.00	06.00	EL/OL	11KV Insulator Failure	No
4		Mattampally	Allipuram	11KV	Huzurnagar	03.00	09.00	06.00	E/L	10KVA DTR failure	No
5		Mamidal	Godavarigudem	11KV	Nalgonda	10.30	15.00	04.30	E/L	11KV Jumper Cut at Godavarigudem (V)	No
6		Kopple	Kopple	11KV	Nalgonda	06.00	10.40	04.40	E/L	11KV Line Insulator Failed at Koplle (V)	No
7		Arlagaddagudem	Suraram	11KV	Nalgonda	08.40	13.20	04.40	E/L	11KV Jumper Cut	No
8		Narsingbatla	Chennugudem	11KV	Nalgonda	16.20	17.30	01.10	E/L	HT/LT Line Melt	No
9		Gollagudem	Gollagudem	11KV	Nalgonda	16:05	18:20	2:15	E/L	Tree fallen on the Line	No
1	MDK	Pati	My home	11KV	Patancheru	14:10	14:45	0:35		Jumper cut	No
1	RR N	Uddamarry	Senha Farm	11KV	Medchal	0:00	1:30	1:30		11KV Pin Insulator failed at Athili Cheruvu	No
1	RR E	VP Nagar	RK Puram	11KV	Sainikpuri	18:35	19:15	0:40		11Kv Under Ground Cable failure at near Substation	No
2		Tattiannaram	Saroomnagar	11KV	Saroomnagar	16.48	17.48	01.00	EL	No visible fault	No
3		Yadgarpally	Thimaipally	11KV	Keesara	04.45	06.30	01.45		No visible fault	No
1	HYD S	E.N.T	Rang Mahal	11KV	Begumbazar	06.05	09.00	02.55	EL,OL	Cable fault & Breaker problem at SS	Arranged B/F on 11KV C.B.I feeder