

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		10		10		10			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		4		4		4			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>17</b>	<b>0</b>	<b>17</b>	<b>0</b>	<b>17</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988		8		8		8			
3	MDK	107	933	5	16	5	16	4	16	1		1 No.33kv still
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>7</b>	<b>25</b>	<b>7</b>	<b>25</b>	<b>6</b>	<b>25</b>	<b>1</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>7</b>	<b>42</b>	<b>7</b>	<b>42</b>	<b>6</b>	<b>42</b>	<b>1</b>	<b>0</b>	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Badepally	Burgupally	11KV	Jadcherla	13.52	14.50	00.58		B.D.Tree Follen On 11 KV Line Near Burgupally( VI).	-
1	NLG	Kethepally	Korlapahad	11KV	Nalgonda	08.00	10.30	02.30	E/L	11 KV Jumper Cut	-
2		Koppole(K)	Beemavaram	11KV	Nalgonda	11.55	13.15	01.20	E/L	11 KV Jumper Cut	-
3		MT pally	Dathaipalli	11KV	Bhongir	06.00	09.00	03.00	E/L	11kv Insulator & Disk failed at velupally (v) & vankatapur(v) near Thokam chyrru	-
4		Rajapet	Narsapur	11KV	Bhongir	07.00	10.30	03.30	E/L	11kv Insulator failed at Bagampat(v) near 1no & near Narsapur(v) 1no falid	-
5		B Ramaram	Jalalpur	11KV	Bhongir	07.40	11.10	03.30	E/L	11kv Insulator failed at Bagampat(v) near 1no & near Narsapur(v) 1no falid	-
6		Pallerla	kurella	11KV	Bhongir	13.00	16.00	03.00	E/L	SS 3 11kv Insulator failed at near pulai gudem(v)	-
7		Seethyathanda	Seethyathanda	11KV	Miryalguda	08.10	12.20	04.10	E/L	Tree fallen on the line	-
8		Kannekal	Guntipally	11KV	Miryalguda	11.00	13.00	02.00	E/L	11K V Conductor snapped and fallen on the 25KV DTR near Garakuntapalem village	-
1	MDK	Nandigama	Vishaka	11KV	Sangareddy	10.15	11.15	01.00		B/D Due to Jumper Cut	-
2		Cheryal	Kalivemula	11KV	Sangareddy	00.45	08.00	07.15		B/D Due to Insulator Failure	-
3		Burugupally	Burugupally	11KV	Medak	10.05	12.15	02.10		B/D Due to tree branches fallen on the line	
4		Palvancha	Danoora	11KV	Medak	12.00	15.00	03.00		B/D Due to tree branches fallen on the line	
5		Gadipeddapur	Gadipeddapur	11KV	Medak	00.00	06.00	06.00		B/D Due to Insulator Failure	
6		Gadipeddapur	Gadipeddapur	11KV	Medak	01.45	07.35	05.50		B/D Due to tree branches fallen on the line	
7		Rangampet	Rangampet	11KV	Medak	09.20	13.30	04.10		B/D Due to Insulator Failure	
8		Ch Ghanpur	Wariguntham	11KV	Medak	06.30	12.40	06.10		B/D Due to tree branches fallen on the line	
9		Kowdipally	Mohd Nagar	11KV	Medak	00.00	06.00	06.00		B/D Due to tree branches fallen on the line	
10		Seelampally	Seelampally	11KV	Medak	11.15	12.15	01.00		B/D Due to Insulator Failure	-
11		Narsapur	Narayanpur	11KV	Medak	08.05	13.15	05.10		B/D Due to tree branches fallen on the line	-
12		Gavvalapally	S. Kondapur	11KV	Medak	07.00	10.00	03.00		B/D Due to tree branches fallen on the line	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
13	MDK	NSF	Rampur	11KV	Medak	00.00	07.00	07.00		B/D Due to Insulator Failure	-
14		NSF	Chityala	11KV	Medak	00.00	07.00	07.00		B/D Due to Insulator Failure	-
15		Medak	Komtur	11KV	Medak	09.20	11.01	01.41		B/D Due to tree branches fallen on the line	-
16				11KV	Medak	14.05	17.10	03.05		B/D Due to tree branches fallen on the line	-
1	RR N	Guntur Vikas	Kendriya Vihar	11KV	Kukatpally	20.16	21.14	00.58		No Visuble foul	-
2		JDMSS-IV	Auto Stand	11KV	Jeedimetla	12.58	15.40	02.42	EL	11kv line PinInsulater failure at Vijay Modle School, Subhash nagar	-
3		Gowdavelly	Basaragadi	11KV	Medchal	08.05	09.24	01.19		7Nos 11KV Poles damaged at Gynanapur Village	-
4		Bommarajpet	Ponnal	11KV	Medchal	13.40	16.00	02.20		11KV Disc failed at Lenonia Company near Pedda Babu Thota, Ponnal	-
5		ICICI	Bharath Bio Tech	11KV	Medchal	19.20	20.58	01.38		11KV Pin Insulator failed at Jenetic Company	-
6		Aliabad	HBL	11KV	Medchal	19.45	22.45	03.00		11KV Pin Insulator failed at Ratnalayam Temple	-
7		Kolthur	Kolthur	11KV	Medchal	20.10	21.20	01.10		Snake fallen on the 11KV Line at Venkatreddy Poultry Farm	-
8		Athiwelly	IDA	11KV	Medchal	19.35	21.20	01.45		No Fault	-
9		Town Medchal	Balaji Nagar	11KV	Medchal	20.35	21.40	01.05		11KV Pin Insulator failed at Balaji Nagar	-
10		Devarayamjal	Kottapet	11KV	Medchal	21.30	23.55	02.25		11KV Pin Insulator failed at Devarayamajal Village	-
1	RR E	Vasanthapuri	Durga Nagar	11KV	Sainikpuri	15.40	16.45	01.05		Iron reku fallen on 11Kv line at Bavarchi Hotel Mirzalguda (AE/Mirzalguda)	-
2		MOTHER DAIRY	VEERABANDRA NAGAR	11KV	SAROORNAGAR	15.03	17.40	02.47	EL	11KV LINE PERLLING NO FALT	-
3		Balaji nagar	Sai baba	11KV	Keesara	13.58	14.38	00.40		Tree fallen on 11kv line at Bhajrang nagar	-
1	HYD N	Zamistanpur	MCH Market	11KV	V	04.18	05.20	01.02	EL,OL-R&Bph	Sparkings in R.M.U at P.R Nagar	-
2		Bhudevi Nagar	Yadamma Nagar	11KV	VI	14.40	15.45	01.05	EL	Disc Insulator flash over at Muthyam Reddy Water Plant	-
3	HYD S	Miralam	Hasan Nagar	11KV	III	22.15	23.55	01.40	EL,OL-Rph	Tree branches fallen on lines & Snapped HT Line at Ganesh PT	-
4		Kanchanbagh	I.S Sadan	11KV	VIII	12.52	14.40	01.48	EL	Auto Reclosure Jumper touching to Pole at Royal Sea Hotel	-

## TSSPDCL - LMRC / Corporate office

Date: 11.06.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	leeza	Mitta Doddy	33kv	Gadwal	09.45	11.40	01.55	OL	B Phase LA Blast at 132KVSS	Mitta Doddy	-
2		220/33KV SS Singotam	Narsaipally	33kv	Nagarkurnool	13.33	16.00	02.27	OL	Tree fallen on the Line	Narsaipally	-
1	MDK	Narsapur	RWS	33kv	Medak	20.45	00.00	03.15		No Visible fault	RWS	-
2		Medak	Nagapur	33kv	Medak	18.09	18.50	00.41		B/D Due to Jumper Cut	Nagapur	-
3		Jogipet	Chitkul	33kv	Sangareddy	06.40	09.45	03.05		B/D Due to Jumper Cut	Chitkul	-
4		Patancheru	Shathavahana	33kv	Sangareddy	02.40	04.40	02.00		B/D Due to Conductor Snapped	Shathavahana	-
5		Sadasivapet	Jogipet	33kv	Sangareddy	01.20	07.25	06.05		B/D Due to Jumper Cut	Jogipet	-