

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		12		12		12			
6	RR(N)	54	550	3	37	3	37	3	37			
7	RR(E)	168	403		13		13		13			
8	Hyd	194	1044	1	40	1	40	1	40			
	Total	606	3055	4	102	4	102	4	102	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	7	3	7	3	7	3			
2	NLG	144	988	3	23	3	23	3	23			
3	MDK	107	933	1	9	1	9	1	9			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	11	35	11	35	11	35	0	0	
	Grand Total	1082	6468	15	137	15	137	15	137	0	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Jaklair	33KV	Mahabubnagar	00.15	13.30	13.15	EL	Tree branch fallen on the line at Lingampally village	Jaklair	Alternate Supply Arranged from 33KV Gunmukla 4:40HRS
2		Kothur	Thimmapur	33KV	Jadcherla	02.45	07.45	05.00	EL	Jumper damaged near Vinayaka Company	Thimmapur	-
3		Kothur	Manasarover	33KV	Jadcherla	07.55	11.25	03.30	EL	Company internal fault	Manasarover	-
4		Kothur	Kothur	33KV	Jadcherla	00.20	02.30	02.10	EL	Damaged Jumper Replacment	Kothur	-
5		Alampur	Unndavelly	33KV	Gadwal	06.40	08.05	01.25	EL	No visible fault Supply stude OK	Unndavelly	-
6		Amarchinta	Chandragattu Lift	33KV	Wanaparthi	02.25	06.56	04.31	EL	Insulator failed	Chandragattu Lift	-
7		Ghanapur	Lattupally	33KV	Nagarkurnool	03.05	10.06	07.01	EL	3No insulator replacement at Manganoor to Bijinepally SS	Lattupally	Alternate supply arranged from 132KV Nagarkurnool at 8:10Hrs
1	NLG	220KV Miryalaguda	Huzurnagar	33KV	Miryalguda	04.30	08.30	04.00	EL	Due to lighting of 05 Nos insulators flasover		-
2		Choutuppal	Divas ind	33KV	Bhongir	23.00	11.30	11.30	EL	33kv Insulator failde in near Sreene Farmace companey		-
3		Suryapet	Sudhakar PVC	33KV	Suryapet	11.00	14.30	03.30	EL	Breaker Limb failed at 132KV SS Suryapet		-
1	MDK	Zaheerabad	Chota Hyderabad	33KV	Zaheerabad	03.50	06.30	02.40		B/D Due to Jumper Cut	Chota Hyderabad	-
1	RR N	132KV Medchal	33KV Medchal-I	33KV	Medchal	01.10	09.12	08.02		B Phase Jumper & R Phase female Contact Cut & Replaced at ORR		-
2		132KV Medchal	33KV Keshavaram	33KV	Medchal	01.17	05.40	04.23		CT Blast at 33/11KV Medicity SS		-
3		132KV LGM Pet	33KV LGM Pet	33KV	Medchal	12.34	15.59	03.25		Bird fallen on the 33KV Line at Kashawada, Aliabad		-
1	HYD N	132KV J' Hills	Sundew (HT Service)	33KV	Kalyan Nagar	02.45	15.55	13.10	EL,OL-R&Bph	Cable stright through Joint failed Opp Nector Garden, Gaffor Nagar	Sundew (HT Service)	At 03.00 hrs Loads transferred onto 132KV J' Hills - Intime Property

## TSSPDCL - LMRC / Corporate office

Date: 23.06.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gangapur	Industrial	11KV	Jadcherla	03.20	06.20	03.00		DTR Fail near Gangapur	-
2		Janampet	Polkampally	11KV	Jadcherla	06.00	10.00	04.00		DTR Fail near Polkampally	-
3		Kothamolgara	Elkicherla	11KV	Jadcherla	03.50	06.10	02.20		DTR Fail near Elkicherla	-
1	NLG	Tripuraram	Duggepally	11KV	Miryalguda	06.00	10.00	04.00	EL	11KV Jumper cut	-
2		Yacharam	Yacharam	11KV	Miryalguda	02.00	07.00	05.00	EL	Tree fallen on the 11KV Line heavy gale & wing	-
3		Thadakamalla	Thadakamalla	11KV	Miryalguda	02.00	07.00	05.00	EL	Tree fallen on the 11KV Line heavy gale & wing	-
4		Laxmidavigudem	Laxmidavigudem	11KV	Miryalguda	00.00	09.00	09.00	EL	Tree fallen on the 11KV Line heavy gale & wing	-
5		Biravunibanda	Biravunibanda	11KV	Nalgonda	11.10	12.36	01.26	EL	Jumper cut	-
6		Kethepally	Inupamula	11KV	Nalgonda	10.00	11.30	01.30	EL	11 KV Line Melt	-
7		Yerkaraam	Yerkaram	11KV	Suryapet	07.20	10.55	03.35	EL	Insulator failed	-
8		Annaram	Sangem	11KV	Suryapet	12.40	15.30	02.50	EL	Disk failed	-
9		Kandagatla	Gattikal	11KV	Suryapet	10.10	12.30	02.20	EL	Insulator failed	-
10		Tedded	Teeded	11KV	Devarakonda	01.00	08.30	07.30	E/L	Insulator Failed	-
11		Kopple	L.D.Gudam	11KV	Devarakonda	03.00	10.00	07.00	E/L	Conductor Sanpped	-
12		Shivannagudam	R.R.Pally	11KV	Devarakonda	01.00	09.00	08.00	E/L	Tree Fallen & Conductor Sanpped	-
13		Shivannagudam	K.B.Pally	11KV	Devarakonda	01.00	09.00	08.00	E/L	Insulator Failed	-
14		K.M.Pally	Indl	11KV	Devarakonda	01.00	06.00	05.00	E/L	Conductor Sanpped	-
15		Ponugodu	Velidanda	11KV	Huzurnagar	01.30	05.00	03.30	EL	Due tree branch fall on 11Kv line	-
16		Chilukur	Janaki nagar	11KV	Huzurnagar	01.00	04.30	03.30	EL	Due to agl jumper cutted	-
17		Thogarrai	GudiBanda	11KV	Huzurnagar	09.05	10.05	01.00	EL	Due to 11kv Insulator failures	-
18		IDA	Singannagudem	11KV	Bhongir	09.50	10.55	01.05	EL	11kv Insulator failed at New muncipall office near	-
19		Bollepally	Surepally	11KV	Bhongir	00.00	06.00	06.00	EL	11Kv Disk Failed near surepally (v)	-
20		Mr gudem	Baswapur	11KV	Bhongir	07.00	10.35	03.25	EL/OL	11 kv Disc failed in ss 4 LM Saleem 905933924	-
21		Maryala	Mailaram	11KV	Bhongir	06.00	12.30	06.30	EL	11Kv Insulator failde & 11 Line Snapped at Mariyala(v) near Chayru kataa	-
22		Chada	Nanacharipet	11KV	Bhongir	02.00	07.00	05.00	EL	11kv Insulator failde & 11 Line Snapped Near Kasireneey gudam	-
23		Addagudur	Ch.Ramaram	11KV	Bhongir	01.00	07.00	06.00	EL/OL	11 kv Insulator failed near in Chinnapatashala(V)	-
1	MDK	Bollaram-I	Pavan	11KV	Patancheru	00.30	07.00	06.30		B/D Due to Insulator failure Due to heavy Rain	-
2		Bollaram-I	Khaithan	11KV	Patancheru	10.35	14.15	03.40		B/D Due to Insulator failure and CTPT Failure	-
3		Bonthapally	Sampistion	11KV	Patancheru	02.20	07.20	05.00		B/D Due to Jumper Cut	-
4		Gummadidala	Agrobell	11KV	Patancheru	02.15	06.15	04.00		B/D Due to Conductor Snapped	-
5		Dundigal	Annaram	11KV	Patancheru	00.00	09.00	09.00		B/D Due to tree branches fallen on the line Due to heavy rain	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
6		Patancheru	Town Industrial	11KV	Patancheru	01.15	03.40	02.25		B/D Due to Insulator failure Due to heavy Rain	-
7		Shankarampet' R	Kamaram	11KV	Medak	09.30	16.20	06.50		B/D Due to Insulator failure	-
8		Kulcharam	Y. Mandapur	11KV	Medak	08.45	14.30	05.45		B/D Due to Jumper Cut	-
9		Rangampet	Tamploor	11KV	Medak	02.00	10.00	08.00		B/D Due to Insulator failure	-
1	RR S	Kismathpur	Rock church	11KV	RJNR	09.40	10.40	01.00	B/D	11kv Disc Failed at vidya peetam	-
2		Gandham guda	Hydharshakote	11KV	RJNR	01.46	02.45	00.59	B/D	11kv Jumper Touching To 33kv Tower pole at Kingbar hydharshakote	-
3		NPA	Hasan nagar	11KV	RJNR	23.40	03.10	03.30	B/D	11KV Insulator failed at Akber masjid Hasannagar	-
4		NPA	Babulreddy nagar	11KV	RJNR	00.35	04.15	03.40	B/D	11KV Insulator at NSF pharmacy and 11kv Disc failed at Saibabanagar	-
5		Chanda Nagar	Shanti Nagar	11KV	GCB	00.00	01.00	01.00	B/D	11kv Pin-insulator failed at Huda café, Shanti Nagar(Due to heavy rain)	-
6		Gachibowli	GopanPally	11KV	GCB	04.00	06.15	02.15	B/D	11kv Disk failed at Nallagandla Huda, 11kv Jumper cut at SBI Bank, 11kv Pin-insulator failed at Sai Raghavendra	-
7		Papireddy colony	Dubey colony	11KV	GCB	03.20	06.00	02.40	B/D	2 no. 11kv Disk failed at Manikanta Homes , Rayadurgam Nivas and 11kv Pin-insulator failed at Surabhi Colony, Tree branches fallen on the 11kv line at Dubey colony	-
8		L & T	Urdu University	11KV	GCB	00.13	03.30	03.17	B/D	LABSO at Urdu University(Internal Cable problem in University)	-
9		KPHB	KPHB	11KV	Kondapur	00.50	03.40	02.50	B/D	11kv Pin-insulator failed and disk failed at Hanuman temple backside, KPHB	-
10		Balaji Nagar	Dhana Laxmi	11KV	Kondapur	00.13	01.45	01.32	B/D	11kv Disk failed at EWS-107, Road NO-2	-
11		Gachibowli	Mezquity	11KV	Kondapur	00.55	02.10	01.15	B/D	11kv LABS Opened at DLF Clameout company(11kv Pin-insulator failed at Maseed banda)	-
12		Gachibowli	Mezquity	11KV	Kondapur	03.00	04.25	01.25	B/D	11kv LABS Opened at Sai Nehru Hospital(11kv Pin-insulator failed at Selfi Apartment)	-
1		Vijayanagar	Jayanagar	11KV	Kukatpally	00.40	02.00	01.20	EL/OL	Due to rain	-
2		Vijayanagar	Yellammabandda	11KV	Kukatpally	00.45	07.00	06.15	EL/OL	UG Cable failure at Good will Hotal,Yellammabandda	-
3		Somashila	R P Colony	11KV	Kukatpally	03.01	04.20	01.19	EL/OL	T/F Lt side Shart line AB Open at Axford School , RP Colony	-
4		Hudatruckpark	Sri Sai nagar	11KV	Kukatpally	00.30	01.30	01.00	EL/OL	11kv Pin Insulater Failure at R K Aprt. Allwy Colony	-
5		HMT Hills	Addagutta	11KV	Kukatpally	01.55	03.00	01.05	EL/OL	{ Line AB Open }Due to rain	-
6		KPHB	Gowtham Nagar	11KV	Kukatpally	04.10	05.30	01.20	EL	Back Feeding to Haydernagar Feeder	-
7		Mayurinagar	Mayurinagar	11KV	Kukatpally	00.25	02.20	01.55	EL	Due To Rain { Bommarellu T/F HG Fuse Failure }	-
8		Nizampet	Nizampet	11KV	Kukatpally	03.30	04.30	01.00	EL	11kv line Disk failure at NRI Collage	-
9		Vijayanagar	Jalakanya	11KV	Kukatpally	00.40	02.00	01.20	EL	Due To Heavy Rain	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
10	RR N	Bachupally	Sai Nagar	11KV	Kukatpally	01.10	02.30	01.20	EL	11kv Pin Insulater Failure at VNR Collage { line AB Open}	-	
11		JDMSS-II	Phase-IV	11KV	Jeedimetla	00.28	01.33	01.05	EL/OL	Due to rain	-	
12		JDMSS-II	ApuroopaCOlony	11KV	Jeedimetla	00.30	02.05	01.35	EL	Due to rain	-	
13		JDMSS-II	ApuroopaCOlony	11KV	Jeedimetla	03.30	04.30	01.00	EL	Due to rain	-	
14		JDMSS-IV	Axies	11KV	Jeedimetla	06.55	08.10	01.15	EL	Due to rain { 11kv line Jumper Cut at Axies Company }	-	
15		Surarm	Matrix	11KV	Jeedimetla	00.30	02.00	01.30	EL/OL	Due to rain	-	
16		JDMSS-III	USP organic	11KV	Jeedimetla	00.20	01.50	01.30	EL/OL	Due to rain	-	
17		JDMSS-III	Vinayakanagar	11KV	Jeedimetla	03.40	04.40	01.00	EL/OL	Due to rain	-	
18		Aleap	Aleap Cable	11KV	Jeedimetla	02.40	07.00	04.20	EL	Due to rain {11kv Disk failure At Pt 47 Prgathinagar	-	
19		Bahadurapally	Indiramma colony	11KV	Jeedimetla	00.33	07.16	06.43	EL/OL	11kv Line Touchede Channel at Bhadurapally X Road	-	
20		DPPally	IDA	11KV	Jeedimetla	04.30	06.30	02.00	EL	Due To Rain	-	
21		DPPally	Bowrampet	11KV	Jeedimetla	04.35	07.35	03.00	EL	11kv PinInsulater Failure at Bowrampet village	-	
22		DPPally	Ganddimaisamma	11KV	Jeedimetla	04.36	06.36	02.00	EL	Due To Rain	-	
23		Subash Nagar	Jairam Nagar	11KV	Medchal	05.20	06.20	01.00		No Fault	-	
24		Subash Nagar	Ramraj Nagar	11KV	Medchal	11.15	12.20	01.05		Middle Phase AB Switch jumper Cut & Replaced at TNR	-	
25		Kompally	Petbasheerabad	11KV	Medchal	17.05	18.20	01.15		11KV Disc Failed at Tower Line	-	
26		Kandlakoya	Goderj	11KV	Medchal	04.15	07.25	03.10		11KV Disc Failed at Nuziveedu seeds	-	
27		Kandlakoya	KV Reddy Nagar	11KV	Medchal	04.15	07.25	03.10		No Fault	-	
28		Bandamadaram	Srirangavaram	11KV	Medchal	05.10	08.05	02.55		No Fault	-	
29		Bandamadaram	Railapur	11KV	Medchal	05.10	09.25	04.15		10 Nos Disc failed at Railapur Village	-	
30		Town Medchal	Balaji Nagar	11KV	Medchal	03.09	06.05	02.56		11KV Pin Insulator Failed at Surya Nagar	-	
31		Gowdavelly	Ayodhya	11KV	Medchal	05.00	07.00	02.00		11KV Disc Failed at Ayodya (11KV Line AB Switch Opened)	-	
32		Bandamadaram	Rock Sand	11KV	Medchal	05.30	08.10	02.40		11KV Pin Insulator Failed at Rock sand company	-	
33		Yellampet	Yellampet Agl	11KV	Medchal	08.25	10.45	02.20		Tree Branches fallen on the 11KV Line at Yella Reddy T/F	-	
34		Shameerpet	Shameerpet	11KV	Medchal	05.40	07.20	01.40		No Fault	-	
35		Devarayamjal	Kottapet	11KV	Medchal	23.50	00.50	01.00		Tree Fallen on 11KV Line at Jama Thota,Yamjal	-	
36		Kolthur	Vishwa	11KV	Medchal	05.00	09.20	04.20		11KV Disc failed at Hertage, Jaganguda	-	
37		Laxmapur	IDA Laxmapur	11KV	Medchal	08.20	09.50	01.30		11KV Pin Insulator failed at Anantharam Village	-	
1			Polytechnic	Srinivasa Puram	11KV	Habsiguda	04.11	05.14	01.03		11KV Disc failed at St.No.02 Srinivasa Puram	-
2			Cherlapally-I	EC Computer	11KV	Sainikpuri	01.00	02.50	01.50		11Kv Disk failure at near Jail (LM Kashiram)	-
3			Anandbagh	Balram Nagar	11KV	Sainikpuri	03.15	04.45	01.30		11Kv Disk failure on 11Kv Insuletor failure at Anandbagh Chourastha (AE/OP)	-
4			Vinayak Nagar	Devi Nagar	11KV	Sainikpuri	00.27	01.14	00.47		Post of Insuletor failure at Neredmet Hanuman Temple (AE/OP)	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
5	RR E	NN Colony	Jammigadda	11KV	Sainikpuri	05.00	06.00	01.00		11Kv Pin Insulator failure at Jammigadda (LM Balram) due to Heavy Rain	-	
6		Cherlapally-IV	Dinatek	11KV	Sainikpuri	08.00	09.10	01.10		11Kv Disk failure at Padmaja Polimers (AE/Cherlapally)	-	
7		Nagaram	Bandlaguda	11KV	Habsiguda	13.08	13.48	00.40		Lizard fallen on 11kv line near Praja Sai Garden Gate	-	
8		Saketh	Damaiguda	11KV	Habsiguda	04.15	06.40	02.25		11KV Disc failed near Adobe Apartment at Dammaiguda	-	
9		Ghatkesar	HPCL	11KV	Habsiguda	15.00	16.00	01.00		Tree branches fallen on 11kv line at Ghatkesar Main Road	-	
10		Aushapur	Edulabad AGL	11KV	Habsiguda	04.00	15.30	11.30		11KV Polymer Disc failed at Kothaguda	-	
11		Aushapur	NFC Nagar	11KV	Habsiguda	00.00	07.30	07.30		11KV Pin Insulator failed and line cut at NFC Nagar	-	
12		Pocharam	Jodimetla	11KV	Habsiguda	05.30	07.00	01.30		Tree fallen on 11kv line at Jodimetla 'X' Road	-	
13		Keesara	Cheeryala	11KV	Habsiguda	06.53	08.40	01.47		11KV Pin Insulator failed at Godumakunta	-	
1		HYD N	Yellareddyguda	Maruthi Nagar	11KV	X	00.08	01.15	01.07	OL-Rph	No Visible Fault	-
2			Road No.2	Shabdalaya	11KV	X	00.20	02.00	01.40	EL	No Visible Fault	-
3			Macha Bollarum	Balaji Rice Mill	11KV	VI	00.50	02.30	01.40	EL	Kite Sticks fallen on lines near SS	-
4			Prashanth Nagar	Sony Complex	11KV	VI	01.05	02.40	01.35	OL-R&Bph	No Visible Fault	-
5	Yellareddyguda		Maruthi Nagar	11KV	X	01.20	02.40	01.20	EL	Tree branches fallen on lines at Park	-	
6	Chinna Thokatta		Panchavati Colony	11KV	VI	02.08	04.10	02.02	EL,OL-Bph	Disc Insulator flash over at Dhana Laxmi Colony	-	
7	Yellareddyguda		Maruthi Nagar	11KV	X	03.00	04.50	01.50	EL	No Visible Fault	-	
8	Road No.13		Road No.1	11KV	X	04.40	07.30	02.50	EL	Cable fault at New Bajaj Show Room	-	
9	Road No.13		Sai Enclave	11KV	X	05.10	06.47	01.37	EL,OL	Disc Insulator flash over at Amrutha Mall	-	
10	Gymkhana		Rani Bagh	11KV	V	06.20	08.20	02.00	EL,OL-Rph	Disc Insulator flash over at Ayyappa Temple	-	
11	Srinagar Colony		Nagarjuna Nagar	11KV	X	09.50	11.20	01.30	EL,OL-Rph	HT Line snapped at Nalla Pochamma Temple	-	
12	N.I.M.S		Nagarjuna Hills	11KV	X	10.42	12.30	01.48	EL	Water flow in 3way RMU	-	
1	HYD S	Hyderguda	Attapur	11KV	III	00.00	01.35	01.35	EL	Cable fault	Arranged B/F on 11KV Jana Priya OH fdr	
2		Ch' Baradari	Fire Station	11KV	III	00.10	02.40	02.30	EL,OL-Bph	Tree branches fallen on lines at Bindu Sariya	-	
3		Sultan Bazar	Koti	11KV	IX	00.10	02.58	02.48	EL	Cable End Kit failed at Andhra Bank	Arranged B/F on 11KV Esamiya Bazar feeder	
4		Karwan	Tallagadda OH	11KV	IX	00.55	03.15	02.20	EL	AB Switch Jumper cut at Nalla Pochamma Temple	-	
5		C.R.P.F	Barkas	11KV	III	05.30	07.30	02.00	EL,OL-Bph	Disc Insulator flash over at Barkas Bada Masjid	Arranged B/F on 11KV C.R.P.F fdr	
6		Chanchalguda	Chanchalguda	11KV	VIII	05.30	06.50	01.20	EL	Pin Insulator flash over at Chanchalguda	-	
7		Panjasha	Sultan Shahi	11KV	III	05.39	07.00	01.21	EL	Disc Insulator flash over at Sultan Shahi	-	
1		S.D Hospital	Humayun Nagar	11KV	VII	00.06	02.31	02.25	EL	Disc Insulator flash over at Opp: Humayuna Nagar P.S	-	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
2	HYD C	Nizam College	Big Bazar	11KV	I	00.41	08.40	07.59	EL,OL	Moisure formed in R.M.U at M.P Mall Big Bazar	-
3		Golconda	Darga Cable	11KV	VII	01.05	05.20	04.15	EL,OL-Yph	Pin Insulator flash over at Darga	-
4		Toli Chowki	Kala Banglow	11KV	VII	01.05	03.05	02.00	All Indication	HT Line snapped at Hakeempet	-
5		Langer House	Prashanth Nagar	11KV	VII	01.05	04.40	03.35	EL	Cable fault	Arranged B/F on 11KV Military Hospital feeder
6		Chilalguda	Parsigutta	11KV	II	01.15	03.20	02.05	EL,OL-Rph	HG fuse burntout at Ganga Putra	-
7		I.T.I Mallepally	P.S Nagar	11KV	VII	01.30	02.40	01.10	EL,OL	Jumper cut at Water Works DTR	-
8		Nizam College	Little Flower	11KV	I	01.36	04.30	02.54	EL	Tree branches fallen on lines at Chappal Rood	-
9		Toli Chowki	Para Mount Colony	11KV	VII	01.50	04.15	02.25	EL	Pin Insulator flash over at Para Mount Colony	-
10		Golconda	Q.Q Toombs	11KV	VII	02.30	08.45	06.15	EL,OL-Rph	HT Jumper cut at Masjid	-
11		Hyderguda	Urdu Hall	11KV	I	02.35	04.45	02.10	EL	No Visible Fault	-
12		Mothi Mahal	M.D Lines	11KV	VII	02.44	04.28	01.44	EL,OL	No Visible Fault	-
13		Jawahar Nagar	Ashok Nagar	11KV	I	03.10	04.25	01.15	EL	No Visible Fault	-
14		Golconda	Mothi Mahal	11KV	VII	04.55	09.05	04.10	EL,OL-Rph	Cable fault	Arranged B/F on 11KV M.D Lines feeder
15		Bathkammakunta	D.D Colony	11KV	II	05.00	06.30	01.30	EL,OL-Bph	Pin Insulator flash over near Justice Meera Kumari House	-
16		Narayanaguda	City Central Library	11KV	I	06.05	07.40	01.35	EL,OL-Rph	Tree branches fallen on lines at City Central Library	-
17		Bathkammakunta	Shivam Road	11KV	II	07.12	08.40	01.28	OL-Bph	Tree branches fallen on lines at Narasimha Basti	-
18		Golconda	Narayanamma Colleege	11KV	VII	07.20	08.37	01.17	EL,OL-Bph	No Visible Fault	-
19		Golconda	Darga Cable	11KV	VII	07.30	09.30	02.00	EL,OL-Yph	No Visible Fault	-
20		Golconda	Narayanamma Colleege	11KV	VII	08.42	12.00	03.18	EL,OL-Rph	Tree branches fallen on lines at Falcon Valley	-
21		Mothi Mahal	M.D Lines	11KV	VII	09.12	10.14	01.02	EL,OL-Y&Bph	Faulty loads of 11KV Mothi Mahal feeder	-