

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	2	1	2	1	2	1			
	Total	606	3055	2	2	2	2	2	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933	1	7	1	7	1	7			
4	SDPT			1	5	1	5	1	5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	18	2	18	2	18	0	0	
	Grand Total	1082	6468	4	20	4	20	4	20	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.06.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Akaram	Shanthinagar	11KV	Nalgonda	10.40	15.05	04.25	E/L	11KV Jumper cut	-
2		Madgulapally	Kukkadam	11KV	Nalgonda	07.40	13.15	05.35	E/L	11KV Line cut at Marridugdem(V)	-
3		S.V Collage	G.Hotel	11KV	Suryapet	12.30	13.30	01.00	E/L	Bird fallen on the line	-
4		Mukundapuram	Somaram	11KV	Huzurnagar	04.00	07.35	03.35	E/L	11Kv Disck Failed	-
5		Y.Singaram	Y.Singaram	11KV	Huzurnagar	02.30	05.30	03.00	E/L	11Kv Line cut	-
6		Thripuraram	Duggepally	11KV	Miryalagudem	08.30	09.40	01.10	E/L	11Kv Insulator Failed	-
1	MDK	Patancheru	Kanjarla	11KV	Patancheru	05.40	06.40	01.00		BD due to Jumper cut	-
2		Gangaram	Gangaram	11KV	Medak	22.10	13.10	15.00		BD due to INSULATOR FAILED	-
3		Minpur	Kurthiwada	11KV	Medak	22.00	10.00	12.00		B/d due to 11 KV line cut.	-
4		Minpur	Annaram	11KV	Medak	01.00	06.00	05.00		BD due to INSULATOR FAILED	-
5		Gandhariaply	Gandharpally	11KV	Medak	11.00	13.10	02.10		BD due to INSULATOR FAILED	-
6		Gandhariaply	Jaipuram	11KV	Medak	08.46	10.27	01.41		B/d due to 11 KV line cut.	-
7		Alladurg	Reddypally	11KV	Medak	16.03	17.17	01.14		B/d due to LT line cut.	-
1	SDPT	Pedda Kodur	Chinna Kodur	11KV	SDPT	16.30	17.00	00.30		Insuletar Fail	-
2		33/11KV SS AKUNOOR	DOMMATA	11KV	SDPT	11.30	20.30	09.00		B/D TREEE BRANCH FALLEN	
3		33/11KV SS DHARMARAM	Nandaram	11KV	SDPT	00.00	05.00	05.00		B/D INSULATER FAILED	
4		33/11KV SS BEJJANKI	RWS	11KV	SDPT	10.00	11.00	01.00		B/D INSULATER FAILED	
5		33/11KV SS KOMURAVELLY	KADAVERGU	11KV	SDPT	19.17	00.00	04.43		HAND TRIP	
1	RR N	Yellampet	IDA	11KV	Medchasi	09.30	10.00	00.30	BD	Tree Branches fallen on the 11KV Line at DRS	-
1	HYD C	Langer House	Military Hospital	11KV	Mehdipatnam	22.14	00.43	02.29	EL	Cable fault	Arranged B/F on 11KV Jyothi Nagar fdr

TSSPDCL - LMRC / Corporate office

Date: 24.06.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Zaheerabad	Jharasangem	33KV	Zaheerabad	00.00	02.20	02.20		BD due to Jumper cut at 132KV SS	Jharasangem	-
2	SDPT	Husnabad	Husnabad	33KV	Husnabad	19.15	20.10	00.55		B/D same rectify	Husnabad	-
1	HYD N	132KV Erragadda - LV Prasad Marg UG	LV Prasad Marg UG	33KV	Jubilee Hills	09.20	18.49	09.29	EL,OL	End Kit failed at Park Hayath Hotel	LV Prasad Marg UG	-
2	HYD S	132KV Bandlaguda	Amberpet	33KV	Asmangadh	14.40	21.20	06.40	EL,OL-Rph	End Kit failed at Bandlaguda Village	Amberpet	-