

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	7	1	7	1	7			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	1	10	1	10	1	10	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988		5		5		5			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	8	3	8	3	8	0	0	
	Grand Total	1082	6468	4	18	4	18	4	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.06.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Peddmandadi	33KV	Wanaparthi	02.25	13.50	11.25	O/L	Conductor Snapped and Phase to Phase Clear	Peddmandadi	Alternate Supply Arranged From 33KV Veltloor at 2:35Hrs
2		Kalwakurthy	Thanrnikal	33KV	Nagarkurnool	00.28	09.15	08.47	O/L	Tree Removing at The Line & Supply upto Gundoor SS	Thanrnikal	-
1	MDK	Sadashivapet	Munipally	33KV	Sangareddy	12.10	13.20	01.10		B/D due to Tree Branches fallen on the line near Munipally.	Munipally	-
1	RR N	Medchal	Bandamadaram	33KV	Medchal	12.36	14.02	01.26	BD	Tree fallen on the 33KV Line at Kandlakoya Village	Bandamadaram	-

TSSPDCL - LMRC / Corporate office

Date: 25.06.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bhoothpur	Town	11KV	Jadcherla	14.45	15.45	01.00		11 Kv Insulator Failure Near sheripally Petrol Pump	-
1	NLG	Settipalem	Annapureddy gudem	11KV	Miryalaguda	10.00	17.00	07.00	EL	11KV Conductor snapped near A R Gudem village	-
2		Dirincherla	Somaram	11KV	Huzurnagar	19.30	21.00	01.30	EL	11 kv line snapped at Somaram village	-
3		G.Malkapuram	Chinthalapalem	11KV	Huzurnagar	01.30	02.30	01.00	EL	Insulator failed at Chinthalapalem village	-
4		G.Malkapuram	Tammaram	11KV	Huzurnagar	01.30	05.00	03.30	EL	11 kv line snapped at Tammaram village	-
5		Bopparam	Midthanapally	11KV	Suryapet	08.00	11.10	03.10	EL	Conductor snapped	-
1	MDK	Ismailkhanpet	Erdanoor	11KV	Sangareddy	13.30	16.30	03.00		B/D due to Jumper cut	-
2		Malkapur	Reliance	11KV	Sangareddy	10.48	11.30	00.42		B/D due to Conductor snapped at Gunthapally (V)	-
1	RR N	Vijayanagar	Sapathagiri Colony	11KV	Kukatpally	13.38	18.10	04.32	EL/OL	11kv pin Insulator Failure & 11kv Jumper cut at HP petrol Pump	-
2		Bahadurapally	I D A-II	11KV	Jeedimetla	07.01	08.22	01.21	EL&OL	T/F HG Fuse Cut touched To channel at Ganesha Ice Factory	-
3		Dulapally	Karthikavanam	11KV	Medchal	12.25	13.18	00.53	BD	No Fault(Heavy Wind)	-
4		Pudur	Mallanna Temple	11KV	Medchal	08.40	09.40	01.00	BD	100KVA T/F Copper Patti cut and replaced at Pipes Company	-
5		Devarayamjal	Kottapet	11KV	Medchal	10.30	12.50	02.20	BD	No Fault	-
6		Kandlakoya	KV Reddy Nagar	11KV	Medchal	10.35	12.05	01.30	BD	Tree fallen on the 11KV Line at Kaveri Seeds	-
7		ICICI	Uniq-I	11KV	Medchal	14.31	16.21	01.50	BD	Tree fallen on the 11KV Line at Londya Company	-
1	RR E	Rampally Dayara	Vanneguda AGL	11KV	Habsiguda	16.45	17.25	00.40		Bird fallen on 11kv line at Barsiguda	-
1	HYD S	Panjasha	Gowlipura	11KV	III	07.25	09.25	02.00	OL	AB Cable End Kit fault at Gowlipura Kallu Compound	-
1	HYD C	Industrial Area	Azamabad I.E	11KV	II	08.20	09.45	01.25	EL,OL-Rph	Breaker fault at SS	Arranged B/F on 11KV Vidya Nagar feeder