

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		6		6		6			
	Total	606	3055	0	9	0	9	0	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		5		5		5			
3	MDK	107	933	2	1	2	1	2	1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	6	2	6	2	6	0	0	
	Grand Total	1082	6468	2	15	2	15	2	15	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.06.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Jogipet	G.Peddapur	33KV	Jogipet	22.15.00 (28.06.18)	10.45.00 (29.06.18)	12.30		BD Due to phase to phase & pin insulator fail		-
2		Jogipet	Laxmi sagar	33KV	Jogipet	10.55	12.45	01.50		BD Due to Bird fallen on line		-

TSSPDCL - LMRC / Corporate office

Date: 29.06.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Mattampally	Pedaveedu	11KV	Huzurnagar	01.30	05.30	04.00	E/L	11kv disk failed at Mattampally (v)	-
2		Ananthagiri	Mogalaikota	11KV	Huzurnagar	02.20	07.00	04.40	E/L	11kv disk failed at Mogalaikot (v)	-
3		Repala	Kalakova	11KV	Huzurnagar	02.20	07.20	05.00	E/L	11kv line snapped at Kalakova (v)	-
4		Rajapet	Rajapet Agl	11KV	Bhongir	06.00	09.00	03.00	E/L	11kv (2)No.S Insulator failed near Bedadha krishna Bavi	-
5		Arlagaddagudem	Mangalapally	11KV	Nalgonda	01.30	06.00	04.30	E/L	11 KV Line Jumper Cut at Mangalapally (V)	-
1	MDK	Rajpet	Rajpet	11KV	Medak	07.40	09.55	02.15		Break Down 11 KV Line Cut	-
1	RR N	Devarayamjal	Pothaipally	11KV	Medchal	00.00	01.30	01.30		Tree fallen on the 11KV Line at DMC	-
2		Keshavaram	Uddamarry	11KV	Medchal	16.18	17.28	01.10		63KVA T/F Brass Patti cut and replaced at Keshavaram Cheruvu	-
1	RR E	Aushapur	Edulabad	11KV	Keesar	13.30	15.30	02.00		Line patrolling but no visible fault	-
1	HYD N	Borabanda	Rama Rao Nagar	11KV	Erragadda	15.45	17.00	01.15	EL	Cable fault at Peeli Darga	Arranged B/F on 11KV Ganesh Nagar fdr
1	HYD S	Panjasha	Sultan Shahi	11KV	Charminar	03.50	04.56	01.06	EL,OL	Breaker problem at SS	Arranged B/F on 11KV Shahjahan Hotel fdr
2		Seetharambagh	Dattatreya Nagar OH	11KV	Begumbazar	12.38	14.10	01.32	OL-Bph	Kite Sticks fallen on lines at Dattatreya Ngr	-
3		Seetharambagh	Hari Darga	11KV	Begumbazar	13.12	14.15	01.03	OL-R&Bph	Tree branches fallen on lines at Natraj Nagar	-
1	HYD C	I.T.I Mallepally	Zaheera Masjid	11KV	Mehdipatanam	12.58	14.25	01.27	EL	Tree branches fallen on lines at NMDC Chaina Bazar	-
2		Narayanguda	City Central Library	11KV	Saifabad	13.05	14.30	01.25	EL,OL-Bph	No Visible fault	-