

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360		2		2		2			
7	Hyd	186	1014		2		2		2			
	Total	504	2929	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948									
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	0	0	0	0	0	0	0	0	
	Grand Total	908	6149	0	5	0	5	0	5	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.03.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Gowdavelly	IDA	11kv	Medchal	00.00	03.00	03.00	BD	11KV Line Cut and replaced near HP Petrol Bunk, Basaragadi Village	-
1	RR E	MARUTHI NAGAR	ASTALAXMI	11kv	SAROORNAGAR	14.45	15.53	01.08	EL	11KV END KIT FALL ON DTR AT ASTALAMI VENINEWU	-
2		Narapally	Narapally	11kv	Habsiguda	17.30	19.30	02.00		Pin Insulator fallen on Cross aram at back side of MC downales	-
1	HYD S	Malakpet	Noorkhan Bazar	11kv	Asmangadh	13.58	23.25	09.27	All Indication	Cable fault at Noorkhan Bazar	14:50 Hrs partial fdr charged (4No DTR's kept off)
2	HYD N	R.P.Nilayam	Nagadevatha	11kv	Secunderabad	22.58	00.40	01.42	EL,OL-Rph	HT Serivce fault at Military Area	23:08Hrs partial fdr (30%) arranged B/F on 11KV R.K.Puram fdr

TSSPDCL - LMRC / Corporate office

Date: 04.03.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBN				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RR S				NIL							-
5	RR N				NIL							-
6	RR E				NIL							-
7	HYD				NIL							-