

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360									
7	Hyd	186	1014	1	2	1	2	1	2			
	Total	504	2929	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		2		2		2			
3	MDK	87	828		2		2		2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	0	4	0	4	0	4	0	0	
	Grand Total	908	6149	1	7	1	7	1	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.03.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Velugupally	Velugupally	11KV	Suryapet	13:00	15:10	2:10	EL	Insulator failed	No
2		Y.Singaram	Y.Singaram	11KV	Huzurnagar	13.08	16.15	03.07	EL	11KV Line cut near Y.Singaram village	No
1	MDK	Sardhana	Sardhana	11KV	Medak	11:32	12:50	1:18		Tree branch fallen on the line	No
2		Narsapur	Reddypally	11KV	Medak	02.00	07.00	05.00		Jumper cut	No
1	RR N	Vijayanagar Colony	AS Raju Nagar	11KV	Kukatpally	22:05	23:05	1:00		AB cable end kit failed at Vivekananda Nagar	No
1	HYD S	C.R.P.F	Balapur	11KV	Charminar	16.15	18.25	02.10	EL,OL-Bph	Cable fault at Balapur	(18:20) Partial feeder added on 11KV Barkas fdr & (18:25) remaining loads added on 11KV Baba Nagar feeder
2		Aliyabad	Boys Town	11KV	Charminar	17:26	18:43	1:17	OL	Cable fault at Aliabad	Arranged B/F on 11KV Masrath Functional Hall feeder

TSSPDCL - LMRC / Corporate office

Date: 08.03.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD N	132KV Madhapur	Devbhoomi	33KV	Kalyan Ngr	08.20	18.00	09.40	OL-R&Bph	RMU Fire catch near 132KV Madhapur SS	Devbhoomi	No