

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360		1		1		1			
7	Hyd	186	1014									
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1	1	1	1	1	1			
2	NLG	150	948		1		1		1			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>1</b>	<b>6</b>	<b>1</b>	<b>6</b>	<b>1</b>	<b>6</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 09.03.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kavarampet	Bandamidipally	11KV	Jadcherla	08.04	10.04	02.00		Due to 11KV Insulator failed near Bandamidipally (V)	No
1	NLG	Narsingbatla	Gadibaigudem	11KV	Nalgonda	4:00	8:00	4:00	E/L	11KV Jumper cut at Garbaigudem (V)	No
1	RR S	Kokapet	Ocean park	11KV	Ibrahimbagh	13:26	15:15	1:49		No visible fault	No
1	RR N	Jeedimetla SS-I	Phase-V	11KV	Jeedimetla	3:00	3:55	0:55	EL/OL	11kv line AB Cable End kit Failure at Vinayaka Chemical at Phase-V	No
2		GP Pally	Malla Reddy	11KV	Medchal	06.10	06.55	00.45	BD	Bird fallen on 11KV line at Mallareddy Campus-I	No
1	RR E	Moula-Ali	Mirzagaluda	11KV	Sainikpuri	9:46	10:36	0:50		UG Cable failed at near Trafic Police Station JTC Main Road	No

TSSPDCL - LMRC / Corporate office

Date: 09.03.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Shanthinagar-I	33KV	Gadwal	15.30	17.32	02.02	E/L	Due to 33KV Line Snapped	Shanthinagar-I	At 17:32 hrs. Shanthinagar I feeder load tag on to Shanthinagar II feeder