

Status Report on Breakdowns (Urban / Rural)**Urban**

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 48 | 158 | | | | | | | | | |
| 2 | NLG | 18 | 406 | | | | | | | | | |
| 3 | MDK | 92 | 383 | | | | | | | | | |
| 4 | RR(S) | 40 | 201 | | | | | | | | | |
| 5 | RR(N) | 82 | 407 | | 1 | | 1 | | 1 | | | |
| 6 | RR(E) | 38 | 360 | | | | | | | | | |
| 7 | Hyd | 186 | 1014 | 2 | 1 | 2 | 1 | 2 | 1 | | | |
| | Total | 504 | 2929 | 2 | 2 | 2 | 2 | 2 | 2 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|-------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 110 | 969 | | | | | | | | | |
| 2 | NLG | 150 | 948 | | 3 | | 3 | | 3 | | | |
| 3 | MDK | 87 | 828 | | 3 | | 3 | | 3 | | | |
| 4 | RR(S) | 31 | 338 | | | | | | | | | |
| 5 | RR(N) | 8 | 48 | | | | | | | | | |
| 6 | RR(E) | 18 | 89 | | | | | | | | | |
| | Total | 404 | 3220 | 0 | 6 | 0 | 6 | 0 | 6 | 0 | 0 | |
| | Grand Total | 908 | 6149 | 2 | 8 | 2 | 8 | 2 | 8 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Date: 13.03.2018

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|--|-----------------------------------|
| 1 | NLG | Gudimalkapuram | Chintalapalem | 11KV | Huzurnagar | 05.00 | 07.20 | 02.20 | E/L | 11Kv Jumper cut near Chintalapalem (v) | - |
| 2 | | Cheedella | Gajula Malkapuram | 11KV | Suryapet | 08.15 | 10.00 | 01.45 | E/L | HT/LT Line Melt | - |
| 3 | | Kattangur | Mallaram | 11KV | Nalgonda | 11.10 | 13.50 | 02.40 | E/L | 11Kv Line Insulator Failed | - |
| 1 | MDK | Thogita | Kuchanpally | 11KV | Medak | 09.30 | 12.00 | 02.30 | | B/D due to 11 KV insulater fail | - |
| 2 | | Kanchanpally | Lingampally | 11KV | Medak | 08.33 | 09.16 | 00.43 | | B/D due to 11 KV jumper cut. | - |
| 3 | | Shankarampet | Kolapally | 11KV | Medak | 06.05 | 11.30 | 05.25 | | B/D due to 11 KV jumper cut. | - |
| 1 | RR N | Kompally | Dholari Dhani | 11KV | Medchal | 06.25 | 07.00 | 00.35 | BD | Tree Fallen on 11KV Line at Bondalagadda | - |
| 1 | HYD S | Attapur | Shareef Nagar | 11KV | III | 17.15 | 18.50 | 01.35 | EL,OL-Rph | Cable fault at Aasad Baba Nagar | Arranged B/F on 11KV N.M.Guda fdr |

TSSPDCL - LMRC / Corporate office

Date: 13.03.2018

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|-----------------------|---|
| 1 | HYD N | 132KV Chilalguda | Clock Tower (Idle) | 33KV | Nehru Ngr | 08.36 | 09.34 | 00.58 | EL | Old Cable End Kit failed at new Boiguda Railway Bridge | Clock Tower (Idle) | ----- |
| 2 | | 132KV Gunrock | Chinna Thokatta | 33KV | Nehru Ngr | 10.03 | 10.15 | 00.12 | OL | Cable damaged by EHT wing near 132KV Gunrock SS Compound Wall | Chinna Thokatta | Loads transferred onto 33KV Gunrock - Bowenpally feeder |