

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234									
5	RR(N)	54	550									
6	RR(E)	168	403		2		2		2			
7	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>5</b>	<b>1</b>	<b>5</b>	<b>1</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 21.03.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Alampur	33KV	Gadwal	07.23	08.14	00.51	E/L	Flash Over Disc Replacement	Alampur	-

TSSPDCL - LMRC / Corporate office

Date: 21.03.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Balanagar	Gouthapur	11KV	Jadcherla	08.40	11.40	03.00		Bird fallen on 11 kv line near Bodajanampet	-
1	NLG	Penpahad	S.R.Palem	11KV	Suryapeta	07.30	10.15	02.45	E/L	Jumper cut	-
2		Ananthagiri	Ameenabad	11KV	Huzurnagar	12.00	14.00	02.00	E/L	Jumper cut	-
3		Ghanapuram	Polkampally	11KV	Devarakonda	08.10	10.45	02.35	E/L	Jumper cut	-
4		Pamanagundla	Yerrasanigudem	11KV	Nalgonda	09.00	10.30	01.30	E/L	11 KV Jumper cut	-
1	RR E	Bandlaguda	Chanikyapur	11KV	Sarrornagar	12.01	13.30	01.29	EL/OL	11KV Line Cut	-
2		Peddamberpet	Peddamberpet	11KV	Sarrornagar	11.15	11.55	00.30	EL/OL	11KV Insulator failed	-
1	HYD N	Begumpet	Yellamma Temple	11KV	IV	21.15	23.05	01.50	EL	Cable End Kit fault at Liketha Apartment	(22:15) partial fedder charged Stood OK