

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234									
5	RR(N)	54	550		3		3		3			
6	RR(E)	168	403									
7	Hyd	194	1044	1	1	1	1	1	1			
	Total	606	3055	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	Total	476	3413	0	3	0	3	0	3	0	0	
	Grand Total	1082	6468	1	7	1	7	1	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.03.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Kuchur	11KV	Jadcherla	08.30	11.55	03.25		11KV Wire Cut near at kuchur (V)	-
1	NLG	Gaddipally	Kutubshapuram	11KV	Huzurnagar	07.50	11.40	03.50	E/L	11kv line snapped at Kutubshapuram (v)	-
2		Mattapally	Mattapally Town	11KV	Huzurnagar	10.50	12.50	02.00	E/L	11Kv Phase to Phase Touched At Mattapally Town	-
1	RR N	JDMSS-I	phase-I	11KV	Jeedimetla	08.45	10.15	01.30	EL	11kv lne Jumper Cut, Touched the Chanal at Remady Company,phase-I Line	-
2		DPPally-II	Indo-fab	11KV	Jeedimetla	08.20	09.45	01.25	EL	11kv lne Jumper Cut, & Co-ca Net brancesh Fallon the 11kv line at 120 Colony	-
3		Medchal	IDA Kandlakoya	11KV	Medchal	01.10	02.50	01.40	BD	11KV Line Cut & replacement near Sarvotham Company	-
1	HYD N	Road No.12	Road No.12	11KV	Jubilee Hills	03.00	04.45	01.45	EL,OL	Post type Insulator damaged at Road No.12	Arranged B/F on 11KV Sri Ram Nagar fdr

TSSPDCL - LMRC / Corporate office

Date: 25.03.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD N	132KV Chilalguda	Monda Market	33kv	Clock Tower	04.00	04.10	00.10	EL,OL	Cable Joint failed at Gandhi Hospital backside	Monda Market	Loads transferred onto 132KV Gunrock SS via 33KV Nehru Nagar fdr