

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234									
5	RR(N)	54	550		2		2		2			
6	RR(E)	168	403									
7	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	Total	476	3413	0	7	0	7	0	7	0	0	
	Grand Total	1082	6468	0	10	0	10	0	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 28.02.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kaverammamet	Bandamidipally	11KV	Jadcherla	13.40	14.30	00.50		Tree fallen on the line near Macharam	-
1	NLG	Eduloor	Munukuntla	11KV	Nalgonda	13.00	14.20	01.20	E/L	Jumper cut	-
2		Pamanagundla	Ismailpally	11KV	Nalgonda	11.30	13.40	02.10	E/L	11KV line milting	-
3		Avanthipuram	Gudur	11KV	Mirylaguda	05.30	10.00	04.30	E/L	HT /LT lines touched each other	-
4		G T Giri	Gumpura Thirumalagiri	11KV	Suryapet	15.15	16.30	01.15	E/L	Insulator failed near SS-5	-
5		Garidepally	Garidepally town	11KV	Huzurnagar	15.55	17.10	01.05	E/L	11 kv line snapped at Garidepally village	-
6		N B Gudem	Dorakunta indl	11KV	Huzurnagar	14.40	17.20	02.40	E/L	11 KV line snapped at Dorakunta village	-
1	RR N	Medicity	Munirabad	11KV	Medchal	00.50	03.10	02.20	BD	11KV Pin Insulator Failed at Munirabad Village	-
2		UMCC	Mahadevpuram	11KV	Medchal	01.34	02.04	00.30	BD	Layout(11KV UG Cable Failed at Mallareddy	-
1	HYD N	R.P.Nilayam	Venkatapuram	11KV	VI	14.05	15.22	01.17	EL	UG Cable damaged at Venkatapuram	-