

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	2	7	2	7	0	0	
	Grand Total	1082	6468	2	11	2	11	2	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.05.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nemmani	Nalakunta	11KV	Nalgonda	11.30	12.30	01.00	E/L	11KV Insulator Failure	-
2		Edulur	Garlabavigudem	11KV	Nalgonda	06.00	04.00	02.00	E/L	11kv Line Jumper Cut	-
3		Mushampally	Erigantipally	11KV	Nalgonda	05.45	02.00	03.45	O/L	11kv Line Jumper Cut	-
4		Thoragal	Thoragal	11KV	Nalgonda	06.00	10.15	04.15	O/L	11kv Line Jumper Cut	-
5		Rayanaguda	Rayanaguda	11KV	Nalgonda	07.00	10.30	03.30	O/L	11kv Line Jumper Cut	-
6		Nagaram	Wardhamanu kota	11KV	Suryapet	04.50	07.30	02.40	E/L	Conductor snapped	-
7		Mukundapuram	Somaram	11KV	Huzurnagar	07.35	08.47	01.12	E/L	11 kv line snapped at Somaram village	-
1	RR N	J D M SS-IV	AAImatha	11KV	Jeedimetla	13.20	15.35	02.15	BD	11kv line Snapped & 2no Jumper Cut at Govt School, Saipuj Wines , Bhagyalaxmi Colony	-
2		Shameerpet	Devarayamjal	11KV	Medchal	06.05	07.40	01.35	BD	25KVA T/F Failed at Ice Factory, Thumkunta	-
1	RR E	Moula-Ali	HCL	11KV	Sainikpuri	07.42	08.35	00.53		Bird fallen on 11Kv line at Krishna Nagar Road No.1 (Foc Naresh)	-
1	HYD S	Karwan	Jiyaguda OH	11KV	Begumbazar	10.12	11.45	01.33	EL	O/G AB Switch Insulator flash over at SS & Cat fallen on DTR at Bada Banda	Arranged B/F on 11KV R.S Temple fdr

TSSPDCL - LMRC / Corporate office

Date: 05.05.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	G R Cable	33KV	Jadcherla	17.02	18.57	01.55	E/L	33KV Bus section L/C GR cable Y Phase Bus isolator female & Male midile post of insulator replaced new one	Balanagar	-
2		Kothru	Thimmapur	33KV	Jadcherla	03.30	10.05	06.35	EL & O/L	Line Petroling MSN Company AB Switch Open No visibule fault Supply Stud OK	Kothru	-