

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988	1	4	1	4	1	4			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	5	4	5	4	5	0	0	
	Grand Total	1082	6468	4	12	4	12	4	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.05.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgara	Elikicherla	11KV	Jadcherla	10.20	11.45	01.25		B.D.11 KV Jumper Cut Touched BY The Cross Arm Near Elikicherla(Vi).	-
1	NLG	Pamangundla	Pittampally	11KV	Nalgonda	10.05	11.15	01.10	E/L	11kV Line Jumper Cut	-
2		Akaram	Vaddipamula	11KV	Nalgonda	11.00	12.30	01.30	E/L	11KV Insulator Failure	-
3		Alair	Ekurthi	11KV	Bhongiri	01.45	04.45	03.00	E/L	25KVA DTR Failed ikuthi(v)	-
4		Bollepally	Jampally	11KV	Bhongiri	08.20	10.55	02.35	E/L	11kV insultaer failed & disc failed	-
1	RR S	IIIT	IVRCL	11KV	Gachibowli	16.33	17.55	01.13		LAB Switch female failed at TNGO'S colony	-
1	RR N	Devarayamjal	DMC	11KV	Medchal	09.05	10.25	01.20	BD	Bird Fallen on 11KV Line at Rajender Poultry farm, Yamjal	-
2		Kolthur	Kolthur	11KV	Medchal	18.00	18.40	00.40	BD	11KV Jumper cut & replacement at Bhagi Reddy thota	-
1	HYD N	LV Prasad Marg	Annapurna	11KV	X	03.50	05.40	01.50	EL,OL-Bph	Cable End Kit failed at More Super Market	Arranged B/F on 11KV Venkatagiri W.W. fdr
2	HYD S	Gosha Mahal	M.J Market	11KV	IX	02.15	04.15	02.00	EL,OL-Y&Bph	Cable fault at Malakunta	Arranged B/F on 11KV Osmangunj fdr
3		Seetharambagh	Dattatreya Nagar OH	11KV	IX	06.15	07.50	01.35	EL,OL	DTR fault at Seetharambagh	-----
4		Jiyaguda	Nalla Pochamma Temple	11KV	IX	10.50	12.12	01.22	EL,OL-Bph	No Visible fault	Arranged B/F on 11KV Tallagadda OH fdr

TSSPDCL - LMRC / Corporate office

Date: 06.05.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Achampet	Amrabad	33KV	Narayanapet	02.05	07.35	05.30	E/L	for Pin Insulater Replacement at Rangapur	Amrabad	-
2		Jadcherla	Kothru	33KV	Thimmapur	23.45	07.20	07.35	EL & O/L	Jansan & Jansan companny Internal Problem	Kothru	-
						5/5/2018	5/6/2018					-
1	NLG	Nalgonda	Panagal	33KV	Nalgonda	08.40	09.30	00.50		Insulator failed	Panagal	-
1	MDK	Pashamailaram	Manjeera	33KV	Sangareddy	05.25	08.50	03.25		B/D due to Insulator fail	Manjeera	-