

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	3	4	3	4	3	4			
6	RR(N)	54	550		10		10		10			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>3</b>	<b>18</b>	<b>3</b>	<b>18</b>	<b>3</b>	<b>18</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	(Within 24)		(Above 24)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	8		8		8				
2	NLG	144	988		5		5		5			
3	MDK	107	933	2	9	2	9	2	9			
4	SDPT				7		7		7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>10</b>	<b>21</b>	<b>10</b>	<b>21</b>	<b>10</b>	<b>21</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>13</b>	<b>39</b>	<b>13</b>	<b>39</b>	<b>13</b>	<b>39</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 09.05.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Narayanpet	33KV	Narayanpet	17.55	22.00	04.05	E/L	Due to Heavy Wind&Rain	Narayanpet	Alternate Supply Arranged From Appakpally
2		Marikal	Devarkadra	33KV	Narayanpet	19.15	19.16	00.01	E/L&O/L	Due to Heavy Wind&Rain	Devarkadra	Alternate Supply Arranged From 33KV Koukuntla
3		Marikal	Koilkonda Water Gridd	33KV	Narayanpet	16.30	23.30	07.00	E/L&O/L	Due to Heavy Wind&Rain	Koilkonda Water Gridd	Alternate Supply Arranged From 33KV Kondapur
4		Ghanapur	Solipur	33KV	Wanaparthy	19.44	22.45	03.01	E/L	Due to Heavy Wind&Rain	Solipur	Alternate Supply Arranged From Shahpur
5		Wanaparthy	Rajapur	33KV	Wanaparthy	19.05	00.00	04.55	O/L	Due to Heavy Wind&Rain Not Rectified	Rajapur	-
6		Wanaparthy	Kodair	33KV	Wanaparthy	21.30	00.00	02.30	E/L&O/L	Due to Heavy Wind&Rain Not Rectified	Kodair	-
7		Kothur	Thimmapur	33KV	Jadcherla	14.55	20.25	05.30	E/L	Cable Problem Rectification at Railway Track	Thimmapur	-
8		Balanagar	G.R Cable	33KV	Jadcherla	16.10	18.05	01.55	E/L&O/L	Due to Heavy Wind&Rain Isolator Closed at Rangareddy Guda(V)	G.R Cable	-
1	MDK	Singoor	Jack well	33KV	Jogipet	17.25	18.35	01.10		B/d due to Tree branches fallen on the line near Singoor (V)	Jack well	-
2		Jogipet	Laxmi Sagar	33KV	Jogipet	14.00	18.15	04.15		B/d due to Conductor snapped.	Laxmi Sagar	-
1	RR S	Shamshabad	Shamshabad-SHBD	33KV	RJNR	14.20	15.38	01.18	B/D	lmax light tower fallen on 33KV line at Near bus stop	Shamshabad-SHBD	-
2		Shamshabad	Gaganpahad-SHBD	33KV	RJNR	13.55	15.38	01.43	B/D	Flexys fallen on 33KV line (Idle feeder)	Gaganpahad-SHBD	-
3		Shamshabad	Gaganpahad-SHBD	33KV	RJNR	16.30	18.40	02.10	B/D	33KV Insulator failed at SR function hall (Idle feeder)	Gaganpahad-SHBD	-

## TSSPDCL - LMRC / Corporate office

Date: 09.05.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ananthagiri	Shanthi nagar	11KV	Huzurnagar	06.10	08.10	02.00	E/L	Jumper cut	-
2		Velugupally	Keshavapuram	11KV	Suryapeta	06.45	08.30	01.45	E/L	Conductor snapped	-
3		Devarakonda	Devarakonda T1	11KV	Devarakonda	17.10	19.30	02.20	E/L	Wind & Gall	-
4		Devarakonda	Devarakonda T2	11KV	Devarakonda	17.10	20.10	03.00	E/L	LT /HT	-
5		Devarakonda	K.B.pally	11KV	Devarakonda	17.15	19.30	02.15	E/L	Wind & Gall	-
1	MDK	SRD-II	No.3	11KV	Sangareddy	17.10	20.10	03.00		B/d due to Conductor sanpped near	-
2		SRD-II	No.2	11KV	Sangareddy	17.15	20.10	02.55		B/d due to Tree branches fallen on the line near I.B.	-
3		SRD-II	Kosla	11KV	Sangareddy	18.00	21.00	03.00		B/d due to Tree branches fallen on the line near ITI.	-
4		SRD-I	No.1	11KV	Sangareddy	16.25	18.55	02.30		B/D due to Insulator fail. ( heavy wind & rain)	-
5		SRD-I	Tallapally	11KV	Sangareddy	16.25	21.25	05.00		B/d due to Conductor sanpped . ( heavy wind & rain)	-
6		Kistareddypet	Patelguda	11KV	Patanceru	13.05	17.15	04.10		B/D due to Insulator fail.	-
7		Anrich Bollaram	Village feeder	11KV	Patanceru	15.20	18.18	02.58		B/d due to Tree branches fallen on the line	-
8		Jinnaram	Jinnaram	11KV	Patanceru	17.30	19.20	01.50		B/d due to Insulator failed near Jinnaram (V)	-
9		Jinnaram	Kodakanchi	11KV	Patanceru	17.30	19.10	01.40		B/D due to Jumper cut near Kodakanchi (V)	-
1	Siddipet	RAGAVAPUR	BHACHAIPALLY	11KV		13.30	14.30	01.00		POLE BROKEN	-
2		BHADIPADAGA	BADIPADAGA	11KV		18.00	20.00	02.00		11 KV LINE CUT	-
3		CHITTAPUR	CHITTAPUR	11KV		17.10	18.45	01.35		DISC FAILURE	-
4		PEDDA CHIKODE	PEDDA CHIKODE	11KV		17.35	22.00	04.25		TREE BRACHES FALL IN 11KV LINE	-
5		LACHAPET	LACHAPET	11KV		14.43	22.00	07.17		11 KV LINE CUT	-
6		DUBBAK	CHERVPUR	11KV		17.30	18.30	01.00		DISK FAILURE	-
7		RAMAKKAPET	POTHARAM	11KV		16.00	22.00	06.00		11 KV LINE CUT	-
1	RR S	IJM	6th Phase	11KV	GCB	15.40	16.48	01.08		11kv Conductor snapped at Karnatka bank	-
2		Gachibowli	Gopanpally	11KV	GCB	14.15	15.50	01.35		11kv Line twisted at Aparna	-
3		Chandanagar	Taranagar	11KV	GCB	15.30	16.50	01.20		Due to heavy rain and Wind.	-
4		Chandanagar	Rail Vihar	11KV	GCB	15.50	17.00	01.10		Due to heavy rain and Wind.	-
1	RR N	G vikas	Aparana	11KV	Kukatpally	15.32	16.50	01.18		11kv Pin Insultor Failure At Aparana Ready Mix	-
2		Mayurinagar	Prashanthanagar	11KV	Kukatpally	16.15	17.40	01.25		11kv Pole Diamage At Brindavanam Colony	-
3		Chandanagar	Sri ram Nagar	11KV	Kukatpally	15.35	16.35	01.00		Due To Heavy Wind	-
4		Jeedimetla-II	Apuroopa colony	11KV	Jeedimetla	15.39	17.05	01.26		Flexy fallen on the 11kv Line At water tank Apuroopa Colony	-
5		Jeedimetla-II	Kompally Phamma	11KV	Jeedimetla	15.39	17.10	01.31		11kv Jumper Snapped At rasi Flour Mill	-
6		Jeedimetla-II	Phase-4	11KV	Jeedimetla	15.57	17.17	01.20		11kv Endy Kit Failure in Sub station	-
7		Jeedimetla-II	Excels	11KV	Jeedimetla	15.58	17.00	01.02		Due To Heavy Rain & Wind	-
8		Jeedimetla-II	NRSA	11KV	Jeedimetla	16.03	17.15	01.12		Cloth Fallen On the 11kv line At Wing Tools Company Phase-iv	-
9		Athiwelly	Gubba	11KV	Medchal	10.00	11.10	01.10		Lizard Fallen on 11KV Line at Gubba	-

10		Chintal	Surya Nagar	11KV	Medchal	20.15	21.20	01.05		11KV AB Cable end kit failed at SK Gardan Surya nagar	-
1	RR E	TATTIANNARAM	TATTIANNARAM	11KV	SAROORNAGAR	05.30	10.30	05.00	EL	LIZARD FALLEN ON DTR HG FUSE SET AT SHERYA COLLAGE	-
2		MOTHER DAIRY	SHIVAM HILLS	11KV	SAROORNAGAR	01.20	02.20	01.00	EL/OL	11KV POLE DAMGED AT CSR COLONY	-
1	HYD S	Miralam	Tadbun	11KV	III	15.30	17.25	01.55	EL	Cable fault at Polite School	16:58 Hrs Partial fdr charged AB Switch opened at Jama Masjid
1	HYD C	Bathkamma Kunta	Ahobilmutt	11KV	II	16.44	18.44	02.00	EL,OL-Rph	Disc Insulator flash over at Ahobil Mutt Temple	17:40 Hrs Partial fdr charged AB Switch opened at Ahobil Mutt Temple