

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	2	4	2	4	2			
2	NLG	144	988	1	7	1	7	1	7			
3	MDK	107	933	1	3	1	3	1	3			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	12	6	12	6	12	0	0	
	Grand Total	1082	6468	6	16	6	16	6	16	0	0	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kandoor	Kandoor	11KV	Jadcherla	08.20	10.40	01.25		11KV Insulator failed near Kandoor (V)	No
2		Janampet	Polkampally	11KV	Jadcherla	13.00	16.30	01.25		Tree fallen on the 11KV line near Polkampally (V)	No
1	NLG	Akaram	Vallala	11KV	Nalgonda	4:30	5:35	1:05	E/L	Jumper cut	No
2		Koppole	Koppole	11KV	Nalgonda	02.30	03.45	01.15	E/L	Insulator failed	No
3		Bopparam	Kothagudem	11KV	Suryapet	02.00	06.30	04.30	E/L	Disc Failed	No
4		Kudakuda	M.G Nagar Thanda	11KV	Suryapet	03.30	06.10	02.40	E/L	conductor snapped	No
5		Yerkaram	Ramannagudem	11KV	Suryapet	02.30	06.40	04.10	E/L	conductor snapped	No
6		Dirsnapally	Chinnanemila	11KV	Suryapet	02.40	06.20	03.40	E/L	Insulator flashover	No
7		Mukundapuram	Mukundapuram	11KV	Suryapet	3:40	16:50	3:10	E/L	Insulator flashover	No
1	MDK	Chippalthurthy	Chippalthurthy	11KV	Medak	0:00	6:00	6:00		Jumper Cut due to Heavy wind	No
2		Kowdipally	Dharmasagar	11KV	Medak	00.00	07.00	07.00		Conductor Snapped due to Heavy wind	No
3		Cheryal	Kalivemula AGL	11KV	Sangareddy	00.00	06.00	06.00		Conductor snapped due to Heavy wind	No
1	RR N	Kistapur	IDA Hanuman	11KV	Medchal	4:15	6:00	1:45		11KV Conductor snapped at Ravalkole Comman	No
1	HYD N	LV Prasad Marg	Annapurna	11KV	Banjara Hills	08.28	10.15	01.47	EL	No visible fault	Arranged B/F on 11KV Kamalapuri Colony feeder
1	HYD S	Falaknuma	Guntal Shah Darga	11KV	Charminar	09.20	11.30	02.10	EL,OL-Bph	Disc insulator flashed over at Railway Track	No
2		Panjasha	Gulzarhouse	11KV	Charminar	23:55	1:20	1:25	EL,OL	Cable fault at Bandika Adda	No

TSSPDCL - LMRC / Corporate office

Date: 10.05.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	SLC Mills	33KV	Mahabubnagar	16.58	19.57	02.59		Due to Phase to Phase near SE Office M.Nagar	SLC Mills	No
2		Mahabubnagar	Machanpally	33KV	Mahabubnagar	17.56	21.30	03.34	E/L&O/L	Due to Wind&Rain	Machanpally	No
3		Chinnamaroor	Velgonda	33KV	Wanaparthi	16.50	17.00	00.10	E/L	Due to CT Problem	Velgonda	No
4		Gadwal	Maldakal	33KV	Gadwal	14:42	21:10	6:28	E/L	Breaker Rectified at Bijawaram SS	Maldakal	No
1	NLG	Thungathurty	Annaram	33KV	Suryapet	2:50	6:10	3:20		Insulator flashed over	Annaram	No
1	MDK	Narsapur	Arobindo	33KV	Sangareddy	3:30	7:00	3:30		Due to Pin insulator failed	Arobindo	No