

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		6		6		6			
8	Hyd	194	1044	4	1	4	1	4	1			
	Total	606	3055	4	9	4	9	4	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	(Within 24)		(Above 24)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		7		7		7			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	13	2	13	2	13	0	0	
	Grand Total	1082	6468	6	22	6	22	6	22	0	0	

TSSPDCL - LMRC / Corporate office

Date: 16.05.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Maganoor	33KV	Narayanapet	17.50	19.55	02.05	E/L	33Kv Jumper Cut near Chandapur Village	Maganoor	-
1	MDK	Jogipet	Laxmi sagar	33KV	Jogipet	02.18	07.50	05.32		B/D Due to Conductor snapped near At Dakur	Laxmi sagar	-
1	HYD N	132KV Madhapur	Deva Bhoomi-Cable-1	33KV	Kalyan Ngr	01.15	03.00	01.45	EL,OL-R&Bph	Cable punctured by GHMC at Mind Space, Soft sole company	Deva Bhoomi-Cable-1	-
1	HYD S	220KV Shivarampally	Ch' Baradari	33KV	Malakpet	14.26	14.34	00.08	EL,OL-Rph	Cable punctured by GHMC at Famous Garden	Ch' Baradari	Loads transferred onto 33KV Shivarampally - Ch' Baradari OH line
2		220KV Shivarampally	Aliyabad	33KV	Malakpet	14.40	14.55	00.15	EL,OL-Rph	Cable punctured by GHMC at Famous Garden	Aliyabad	Loads transferred onto 33KV Shivarampally - Ch' Baradari OH line
1	HYD C	132KV Asif Nagar	Langer House	33KV	Asif Nagar	06.50	07.02	00.12	OL-Y&Bph	Bph Conductor snapped at Pillar No.77	Langer House	Loads transferred onto 132KV Imlibun SS via 33KV Seeth.Bagh SS

TSSPDCL - LMRC / Corporate office

Date: 16.05.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Palakeedu	Sajjapuram	11KV	Huzurnagr	18.20	20.10	01.50	E/L	11kv line snapped at Sajjapuram (v)	-
2		Keethavarigudem	Kothagudem	11KV	Huzurnagr	06.10	08.30	02.20	E/L	11Kv line snapped at Kothagudem (v)	-
3		Gondiryala	Chimiryala	11KV	Huzurnagr	06.00	09.35	03.35	E/L	11kv jumper open Chimiryala (v)	-
4		Madgulapally	Kukkadam	11KV	Nalgonda	04.50	09.30	04.40	E/L	11KV Insulator Failed	-
5		Kattangur	Bollepally	11KV	Nalgonda	08.10	14.25	06.15	E/L	11KV Jumper Cut	-
6		Marriguda	Konduru	11KV	Devarakonda	14.50	17.00	02.10	E/L	11Kv Conductor Sanpped	-
7		Kothapally	Pedamunigal	11KV	Devarakonda	07.00	08.00	01.00	E/L	11Kv Jumper Cut	-
1	MDK	Venkatraopet	Venkatraopet	11KV	Medak	11.00	11.50	00.50		B/D due to Pin insulator burn.	-
2		Ch Ghanpur	Ch Ghanpur	11KV	Medak	06.30	10.10	03.40		B/D due to AB Switch Problem	-
1	Siddipet	Thotapally	GUNDLAPALLY	11KV	Siddipet	08.50	12.30	03.40		11KV insulator break same rectified	-
2		Komuravelly	Kistampeta	11KV	Siddipet	10.40	16.45	06.05		11KV insulator break same rectified	-
3		Regulapally	Kadavergu	11KV	Siddipet	15.30	16.30	01.00		Due to Branch fallen on 11KV feeder, rectified	-
4		Dhoolmitta	Arjunpatla	11KV	Siddipet	15.20	18.30	03.10		Due to Branch fallen on 11KV feeder, rectified	-
1	RR N	Laxmpur	MC pally	11KV	Medchal	17.00	20.00	03.00	BD	11KV pin insulator at MC pally	-
2		Chandanagar	Shankar Nagar	11KV	Kukatpally	15.40	17.15	01.35	BD	Due To Havy Rain	-
1	RR E	Uppal	Chilaka Nagar	11KV	Habsiguda	23.30	00.20	00.50		11KV UG Cable damaged due to HMWS JCB Work near Andhra Bank at Beerappa Gadda	-
2		MARUTHINAGAR	MORE	11KV	SAROORNAGAR	18.37	20.30	01.53	EL	11KV CABLE TAIL LOADS DIVERTED TO 11KV VIDUYATHNAGAR FEEDER	-
3		Yadgarpally	Cheeryala	11KV	Keesara	17.00	18.30	01.30		Tree fallen on 11kv line at Cheeryala	-
4		CRPF	Chennapur	11KV	Keesara	16.35	17.40	01.05		11KV line twisted at Aradaspally	-
5		Chakripuram	Shilpa	11KV	Keesara	18.10	19.10	01.00		Tree branches fallen on 11kv line at East Gandhi Nagar	-
6		Nagaram	Bandlaguda	11KV	Keesara	16.36	17.18	00.42		Tree branches fallen on 11kv line near Praja Sai Garden	-
1	HYD C	A.S.R.Raju Nagar	A.S.R.Raju Nagar	11KV	VII	07.04	08.20	01.16	EL	33KV Line snapped & fallen on 11KV Line at Pillar No.77	-