

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044	2	4	2	4	2	4			
	Total	606	3055	2	6	2	6	2	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		1		1		1			
3	MDK	107	933		4		4		4			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	5	2	5	2	5	0	0	
	Grand Total	1082	6468	4	11	4	11	4	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 20.05.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Amarchintha	Atmakur	33KV	Wanaparthi	08.25	10.40	02.15		Insulator Damaged Near Atmakur	Atmakur	No
2		Gadwal	Bijwar	33KV	Gadwal	01.30	11.50	10.20		Pin Insulator Damaged near at Sangala (V)	Bijwar	No
1	HYD N	132KV J' Hills	Sundew	33KV	Kalyan Ngr	15.32	15.37	00.05	EL,OL-Bph	Cable joints failed	Sundew	Loads transferred onto 132KV Madhapur SS
1	HYD C	132KV Asif Nagar	Karwan (Langer House)	33KV	Asif Ngr	07.40	07.48	00.08	EL,OL	Cable End Kit failed at 33KV Asif Nagar SS	Karwan (Langer House)	Loads transferred onto 132KV Imlibun SS via 33KV Jiyaguda fdr

TSSPDCL - LMRC / Corporate office

Date: 20.05.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Bairavanibanda	NGK Pally	11KV	Nalgonda	13:25	14:50	1:25	E/L	11KV Line insulator failed	No
1	MDK	Rangampet	Paithra	11KV	Medak	12:00	14:40	2:40		11KV Conductor snapped	No
2		Tekmal	Tamploor	11KV	Medak	07.30	09.30	02.00		11KV Jumper cut	No
3		Sangareddy -Town2	Kosla	11KV	Sangareddy	02.15	04.15	02.00		Tree branches fallen on the line	No
4		Isnapur	IDA- Isnapur	11KV	Sangareddy	04.45	07.55	03.10		Due to breakder problem	No
1	RR N	Subash Nagar	Padma Nagar	11KV	Medchal	6:30	7:25	0:55		11KV Conductor Snapped at Sreeram Nagar	No
2		Shameerpet	Shameerpet	11KV	Medchal	17.00	18.20	01.20		11KV UG Cable failed in SS	No
1	HYD S	Miralam	Madina Masjid	11KV	Charminar	09.50	11.00	01.10	EL,OL-Rph	Cable fault at M.J. Funtion Hall	No
2		Kandikal Gate	Patel Nagar	11KV	Charminar	12:25	14:05	1:40	EL	Cable fault at Patel Nagar	Arranged B/F on 11KV Gowlipura fdr
3		Arundhathi Colony	Moin Bagh	11KV	Charminar	18:30	20:55	2:25	EL,OL	Breaker problem at SS	Arranged B/F on 11KV Patel Nagar fdr
1	HYD C	Industrial Area	R.O.M.	11KV	Azamabad	02.05	03.20	01.15	OL-R&Bph	Cable fault at Garunda Apts	Arranged B/F on 11KV Preventive Medicine fdr