

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	7	0	7	0	7	0	0	
	Grand Total	1082	6468	0	8	0	8	0	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 21.05.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nuthankal	Polumalla	11KV	Suryapet	13.15	15.15	02.00	E/L	11Kv Conductor snapped	-
2		Alingapuram	Raghvapuram	11KV	Huzurnagar	06.00	07.34	01.34	E/L	11kv line snapped at Meegadam pahad thanda (v)	-
3		Koppol (K)	Beemaram	11KV	Nalgonda	08.00	11.00	03.00	E/L	11Kv Line Jumper cut	-
1	SDPT	AKUNUR	DOMMATA	11KV	SDPT	00.00	09.55	09.55		B/D RECTIFIED	-
2		GUGGILLA	THIMMAIPALLY VCB II	11KV	SDPT	14.25	19.13	04.48		BD / INSULATOR FAILED, AND RECTIFIED	-
3		REGULAPALLY	REGULAPALLY	11KV	SDPT	10.05	12.10	02.05		BD/ JUMPPER BURNING, AND RECTIFIED	-
4		REGULAPALLY	MALLAMCHERUVU	11KV	SDPT	12.10	16.45	04.35		BD/ LT LINE CUT, AND RECTIFIED	-
1	RR E	Moula-Ali	Meerpet	11KV	Sainikpuri	14.14	14.44	00.30		Tree branches on Telephone wire fallen on 11Kv line at Thirumala Nagar (LM Venkatesh)	-

TSSPDCL - LMRC / Corporate office

Date: 21.05.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RR S				NIL							-
5	RR N				NIL							-
6	RR E				NIL							-
7	HYD				NIL							-