

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	(Within 24)		(Above 24)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		3		3		3			
3	MDK	107	933	3	4	3	4	3	4			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	7	3	7	3	7	0	0	
	Grand Total	1082	6468	3	10	3	10	3	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.05.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Pashmailaram	APL5	33KV	Sangareddy	09.50	13.25	03.35		BD ue to Conductor snapped	APL5	-
2		Sadashivapet	Munipally	33KV	Sangareddy	11.35	12.40	01.05		BD due to Jumper cut	Munipally	-
3		Narsapur	Reddypally	33KV	Medak	09.45	13.40	03.55		BD due to line melting & Jumper cut	Reddypally	-

TSSPDCL - LMRC / Corporate office

Date: 23.05.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thungathurthy	B Ramaram	11KV	Suryapet	06.00	08.00	02.00	E/L	Insulator failed	-
2		Mattapally	Mattapally	11KV	Huzurnagar	05.45	07.40	01.55	EL	Due to 11Kv Jumper Cutted near Mattapally village	-
3		Pamanagundla	Pittampally	11KV	Nalgonda	09.25	11.30	02.05	E/L	11KV jumper cut	-
1	MDK	Rajpally	Balanagar	11KV	Medak	03.30	08.00	04.30		B/D due to Insulator faile	-
2		Narsapur	Narayanpur	11KV	Medak	08.00	10.00	02.00		B/D due to Tree falan on the conductor.	-
3		Venktraopet	Thunki	11KV	Medak	10.20	12.20	02.00		B/D due to Disc Failed.	-
4		Bollaram-I	NCL	11KV	Sangareddy	09.55	10.45	00.50		BD due to tree fallen on line	-
1	RR N	G Vikas	CoCa-Cola	11KV	KKP	10.12	12.17	02.05	EL/OL	11kv UG Cable Failure OPP Sub Station	-
2		Bandamadaram	Srirangavaram	11KV	Medchal	12.10	13.40	01.30	BD	11KV Line Phase to Phase Touched To Devendhar Reddy Bhavi, Srirangavaram Village	-
1	HYD S	Kandikal Gate	Ashamabad	11KV	III	07.15	08.20	01.05	EL,OL-Rph	Faulty RMU at 3Star, Ashamabad	-