

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		4		4		4			
2	NLG	144	988	1	3	1	3	1	3			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	9	1	9	1	9	0	0	
	Grand Total	1082	6468	1	14	1	14	1	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.11.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Ramannapeta	Aroor	33KV	Bhongiri	13.05	16.50	03.45	E/L	Tree branches fallen on line		-

TSSPDCL - LMRC / Corporate office

Date: 02.11.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Janampet	24 Hours	11KV	Jadcherla	06.15	06.55	00.40		11kv Jumper cut near Vemula	-
2		Annasagar	Tatikonda	11KV	Jadcherla	12.04	12.30	00.26		11KV Wire cut near Tatikonda	-
3		Mothiganapur	Gangadarpally	11KV	Jadcherla	06.40	08.00	01.20		11KV Wire cut near Gangadarpally	-
4		Gangapur	Alwanpally	11KV	Jadcherla	13.10	14.55	01.45		Insulator fail near Alwanpally	-
1	NLG	S.V.College	Synikpuru	11KV	Suryapeta	10.15	11.35	01.20	E/L	11KV Jumper cut	-
2		Rajupeta	Rajupeta	11KV	Nalgonda	09.00	11.16	02.16	E/L	11 KV line jumper cutting	-
3		Kattangur	Mallaram	11KV	Nalgonda	14.10	16.40	02.30	E/L	Insulator failed	-
1	SDPT	Mustyal	Veerannapet	11KV	Siddipet	00.45	05.30	04.45		Due to Insulator failure	-
2		Gagillapur	Gagillapur Agl	11KV	Siddipet	17.05	17.35	00.30		Jumpet cut	-
1	RR N	Jeedimetla SS III	Foxsagar	11KV	Jeedimetla	13.40	15.20	01.40	EL/OL	bird fallen on the 11 kv line opp Kantha Rubbber at Ramreddy nagar	-
1	RR E	Vinayak Nagar	RK Nagar	11KV	Sainikpuri	07.29	08.19	00.50		Bird fallen on 11Kv line at Indian Gas Godham RK Nagar (AE/Anandbah)	-
2		Ramanthapur	Church Colony	11KV	Habsiguda	01.48	02.55	01.07		11KV UG Cable damaged due to JCB Road winding work at Sri Nagar Colony	-
3		Aushapur	Edulabad	11KV	Keesara	16.50	19.10	02.20		11KV line twisted near Krishnamurthy College Backside	-
1	HYD S	Laxmi Nagar	Vinay Nagar	11KV	Asmangadh	12.07	13.28	01.21	W/O Indication	No Visible Fault	-