

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	9	0	9	0	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	7	0	7	0	7	0	0	
	Grand Total	1082	6468	0	16	0	16	0	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.11.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Nawabpet	Rudraram	11kv	Jadcherla	13.05	14.02	00.57		Due to 11KV Line Phase to Phase Near Chennareddy pally	-
1	NLG	Nuthankal	Polumalla	11kv	Suryapet	08.20	09.30	01.10	E/L	11Kv Jumper cut	-
2		Kattangur	Mallaram	11kv	Nalgonda	12.00	16.00	04.00	E/L	11KV Jumper Cut	-
3		Nemmani	Pothinenipally	11kv	Nalgonda	09.35	11.00	01.25	E/L	11KV Insulator Failed	-
4		Nemmani	Merlakunta	11kv	Nalgonda	15.30	17.20	01.50	E/L	HT/LT Lines Melt	-
1	SDPT	Bejanki	Kallepally	11kv	Husnabad	10.20	13.10	02.50		Insulator failed same rectified	-
2		Samudrala	Baswapur	11kv	Husnabad	13.25	15.42	02.17		Insulator failed same rectified	-
1	RR N	Chinthal	Bhagathsingh Nagar	11kv	Medchal	17.40	18.40	01.00	BD	100KVA DTR In coming jumper cut at Bhagathsingh nagar	-
2		UMCC	Mini Industry	11kv	Medchal	14.25	17.35	03.10	BD	11KV AB Cable failed Back feeding from 11KV Sriram nagar feeder	-
3		Devarayamjal	Kottapet	11kv	Medchal	04.30	05.20	00.50	BD	Tree fallen on the 11KV Line at VRL Company	-
1	RR E	Yapral	Yapral	11kv	Sainikpuri	14.25	14.55	00.30		Brid fallen on 11Kv line at LIC Colony (L.Insp Narsimha)	-
2		Narapally	AP Meat	11kv	Keesara	11.02	11.52	00.50		Monkey fallen on 11kv line near Powder Factory	-
1	HYD S	Kanchanbagh	I.S Sadan	11kv	VIII	00.22	01.40	01.18	EL	Cable End Kit fault at New 7B Ground	-----
2		Miralam	Mustafa Nagar	11kv	III	09.40	12.05	02.25	All Indication	No Visible Fault	Arranged B/F on 11KV Ansari Road feeder
3		Aliyabad	Sather Bagh	11kv	III	13.01	14.20	01.19	EL	HT Jumper cut at Sather Bagh New line AB Switch	-----
4		Miralam	MCH Colony	11kv	III	17.35	18.50	01.15	EL	Link Line AB Swtich Jumpers cut at MCH Park	-----

TSSPDCL - LMRC / Corporate office

Date: 04.11.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBN				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RR S				NIL							-
5	RR N				NIL							-
6	RR E				NIL							-
7	HYD N				NIL							-
8	HYD S				NIL							-
9	HYD C				NIL							-