

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>9</b>	<b>1</b>	<b>9</b>	<b>1</b>	<b>9</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 10.11.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Suryapet	B. Chandupatia	33KV	Suryapet	5:00	9:00	4:00	EL	Insulator Flashover	B. Chandupatia	No

## TSSPDCL - LMRC / Corporate office

Date: 10.11.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Ponnakal	Vemula	11KV	Jadcherla	09.35	11.00	01.25		11KV Wire cut near palugu ralla gutta in Vemula (V)	No
1	NLG	G.Yedavally	G.Yadavally	11KV	Nalgonda	6:20	9:20	3:00	EL	HT/LT line melt	No
2		Gundrampally	Apoor	11KV	Nalgonda	04.25	07.15	02.50	EL	Insulator failed	No
3		Rayaniguda	Kankanalapally	11KV	Nalgonda	06.10	09.06	02.56	EL	Jumper cut & Insulato failed	No
4		Pamangundla	Yerrasanigudem	11KV	Nalgonda	05.52	09.10	03.18	EL	AB switch Jumper cut	No
5		Ramadugu	Kupashpa	11KV	Miryalaguda	12.50	14.20	01.30	EL	11KV Jumper cut	No
6		Phanigiri	Phanigiri Agl	11KV	Suryapet	4:30	7:00	2:30	EL	Insulator flashover	No
1	HYD S	Malakpet	Yashoda Hospital	11KV	Asmangadh	01.45	03.12	01.27	EL,OL-Rph	No Visible Fault	Partial feeder charged at 02:40 hrs. & remaining loads added on 11KV Dabeerpura fdr
2		Asmangadh	Saibaba	11KV	Asmangadh	4:10	5:58	1:48	EL,OL,	I/C Cable fault	Arranged B/F on 11KV Tirumala Hills feeder