

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044	1	2	1	2	1	2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		4		4		4			
3	MDK	107	933		5		5		5			
4	SDPT			2	4	2	4	2	4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>13</b>	<b>2</b>	<b>13</b>	<b>2</b>	<b>13</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>15</b>	<b>3</b>	<b>15</b>	<b>3</b>	<b>15</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 19.11.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Palem	Ogodu	11KV	Nalgonda	05.22	09.05	03.43	EL	11KV line cut at nearby village	-
2		T Giri	Indl Express	11KV	Suryapet	13.15	14.20	01.05	EL	Insulator flashover	-
3		Dirsincherla	Somaram	11KV	Huzurnagar	10.30	14.00	03.30	OL	Due to 11Kv line cutted	-
4		Urulugonda	N.S.Puram	11KV	Huzurnagar	16.30	17.50	01.20	EL	Due to 11Kv jumper cutted	-
1	MDK	Cheryal	Julkal	11KV	Sangareddy	07.10	11.05	03.55		B/D Due to Insulator failed	-
2		Bollaram - II	Vasavidatta	11KV	Patancheru	15.50	17.30	01.40		BD due to Conductor snapped near MM rocks	-
3		Gaddapotharam - I	United	11KV	Patancheru	09.10	10.10	01.00		BD due to Conductor snapped	-
4		Gundla Machnoor	Industrial	11KV	Jogipet	00.00	07.50	07.50		BD due to Conductor snapped near MM rocks Company side	-
5		Pothireddypally	Kondareddypally	11KV	Jogipet	06.00	08.30	02.30		B/D due to Jumper Cut Near Kondareddypally(V)	-
1	SDPT	GAGILLAPUR	VALLAMPATLA	11KV	SDPT	12.16	12.56	00.40		BD DUE TO LINE PROBLEM	-
2		MARMAMULA	MARMAMULA	11KV	SDPT	15.00	15.05	00.05		BD DUE TO LINE PROBLEM	-
3		POTHARAM	MIRJAPUR	11KV	SDPT	09.25	11.30	02.05		BD DUE TO LINE PROBLEM	-
4		GOURAVELLY	GUDATIPALLY	11KV	SDPT	00.00	09.45	09.45		BD DUE TO LINE PROBLEM	-
1	HYD N	Lalaguda	Vijaypuri Colony	11KV	Sec'bad	04.00	05.20	01.20	OL-R&Bph	B/o Brass Patti & Twisted Lines at Bondalagadda DTR	-----
2	Hyd C	Golnaka	Moulana Azad Nagar	11KV	Azamabad	05.25	06.49	01.24	EL,OL	RMU fault	Arranged B/F on 11KV Tourist Hotel & 11KV C.C.Shroff Hospital feeder

TSSPDCL - LMRC / Corporate office

Date: 19.11.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Husnabad	Katkur	33KV	Husnabad	02.20	07.55	05.35	BD	SNAKE FALLEN ON LINE	Katkur	-
2		Angadikistapur	Ganeshpally	33KV	Gajwel	11.00	14.00	03.00	OL	33 KV Y-phase Polymer disk failed	Ganeshpally	-
1	HYD C	132KV Imlibun	Jiyaguda Cable-1	33KV	Mehdipatnam	17.10	17.20	00.10	OL-Rph	Tripped on OL-Rphase	Jiyaguda Cable-1	Loads transferred onto 132KV Asif Nagar SS via 33KV A.S.R Raju Nagar fdr