

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		9		9		9			
3	MDK	107	933		2		2		2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	11	0	11	0	11	0	0	
	Grand Total	1082	6468	0	13	0	13	0	13	0	0	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Penpahad	Dubbathanda	11KV	Suryapet	05.00	07.30	02.30	E/L	11KV Insulator flashover	No
2		Bethavolu	Bethavolu	11KV	Huzurnagar	03.00	06.00	03.00	EL/OL	11KV Line Snapped	No
3		Dirincherla	Narsaigudem	11KV	Huzurnagar	06.00	09.00	03.00	E/L	11KV Jumper Cut	No
4		Palakeedu	Sajjapurm	11KV	Huzurnagar	7:00	9:00	2:00	E/L	11KV Jumper Cut	No
5		Garidepally	Ponugodu	11KV	Huzurnagar	09.20	10.20	01.00	E/L	11KV Line Snapped	No
6		Ponugodu	Velidanda	11KV	Huzurnagar	8:48	10:08	1:20	E/L	11KV Line Insulator failed	No
7		Akupamula	Akupamula indl	11KV	Huzurnagar	14.55	15.55	01.00	E/L	11KV Line Snapped	No
8		Urumadla	Elikatte	11KV	Nalgnda	07.00	09.40	02.40	E/L	11KV Line Insulator failed	No
9		Nakrekal	Chandurpatla	11KV	Nalgnda	04.00	08.00	04.00	E/L	11KV Line Jumper Cut	No
1	MDK	Ch.Hyd	Ch.Hyd	11KV	Zaheerabad	4:10	8:40	4:30		Disc failed	No
2		EPIP-I	Chitrakoot	11KV	Patancheru	12.30	13.05	00.35		Jumper cut near Shivaganga Palimar	No
1	RR E	Peerzathiguda	LV-2	11KV	Habsiguda	15:18	17:10	1:52		LV-2 breaker cable fault at SS Yard	Back feeding supply taken from 11KV Parvathapur feeder
1	HYD S	Salarjung	Madina	11KV	Charminar	05.55	07.13	01.18	All Indication	Cable fault & Jumper cut at Madina	Arranged B/F on 11KV Gansi Bazar feeder