

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	1		1		1				
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	1	0	1	0	1	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	7	0	7	0	7	0	0	
	Grand Total	1082	6468	1	7	1	7	1	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.11.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	RR S	ESCI	Prashanti Hills	33KV	Kondapur	13.10	14.15	01.05	0.59375	11kv AB-Cable failed, Backfeeding from Nanakramguda Feeder(ESCI S.S)		-

TSSPDCL - LMRC / Corporate office

Date: 23.11.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Peddathanda	Peddathanda	11KV	Bhongir	10.15	11.50	01.40	E/L	11kv Insulator Fail near Thimapur Villge	-
2		Penpahad	Dubbathanda	11KV	Suryapet	13.30	16.10	02.40	E/L	11Kv Conductor snapped at Dharmarav bore well	-
3		Dondapadu	Kakatiya	11KV	Huzurnagar	11.20	12.00	00.40	E/L	11Kv line cut	-
4		Kodad Indoor	Komarabanda	11KV	Huzurnagar	05.45	07.20	01.35	EL/OL	Bird fall on 11Kv line	-
5		Munagala	Turkagudem	11KV	Huzurnagar	08.30	12.00	03.30	EL/OL	11Kv Jumper cut	-
6		Madgulapally	Kukkadam	11KV	Nalgonda	09.10	11.00	01.50	E/L	11KV Jumper cut	-
1	SDPT	Ramchandrapur	Vinjapally	11KV	Siddipet	09.20	12.20	03.00		BD Due to Insulator failure	